



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T32 LWB P/V 130TDI E4
Colour	Silver
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-05
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-13
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	36
Total items failed	4

MOT #17	2024-02-26 16:15
MOT test number	829004293980
Result	✓ Passed
Next expiry date	2025-03-13
Advice	Coil spring corroded (5.3.1 (b) (i))

MOT #16	2023-03-13 14:12
MOT test number	659286088585
Result	✓ Passed
Advice	Eng covers and undertrays fitted at time of test
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-03-14 16:40
MOT test number	817458034813
Result	✓ Passed

**MOT #14**

2021-01-26 09:45

**MOT test number**

264337029073

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2020-01-25 09:37

**MOT test number**

110092198678

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring worn and offside rear (5.3.1 (b) (i))

**MOT #12**

2019-01-26 08:46

**MOT test number**

598310081087

**Result**

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2018-01-25 08:42

**MOT test number**

742936346208

**Result**

✓ Passed

- Advice** Oil leak
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #10**

2017-01-28 09:03

**MOT test number**

288097863739

**Result**

✓ Passed

- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)

**MOT #9**

2016-01-25 08:45

**MOT test number**

801639134124

**Result**

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both inners (3.5.1i)
- Advice** Parking brake needs slight adjustment
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8**

2015-01-26 08:41

**MOT test number**

586056825087

**Result**

✓ Passed

**MOT #7** 2014-01-17 12:24**MOT test number** 595717214094**Result** ✓ Passed**MOT #6** 2013-01-28 11:54**MOT test number** 408658523047**Result** ✓ Passed**Notice** Main beam high on o/s/f**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #5** 2013-01-26 11:34**MOT test number** 187316523044**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** Main beam high on o/s/f**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2012-01-24 12:50**MOT test number** 118674422454**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)



MOT #3	2012-01-23 15:53
MOT test number	518813822044
Result	✗ Failed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)
Fail	Offside Front Upper Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #2	2011-04-13 15:10
MOT test number	897253401108
Result	✓ Passed

MOT #1	2010-05-06 14:59
MOT test number	402536720128
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
13 March 2025

Tax status	Valid until 1 March
------------	---------------------

Days left	307
-----------	-----

MOT expiry date	13 March 2025
-----------------	---------------

Full MOT history	<a href="#">See MOT history</a>
------------------	---------------------------------





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>WR07ZPX</b>
Plate since	2019-06-29
Current registration	<b>WR07ZPX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-01
Last registration	2024-02-26
Complete history	<a href="#">See info</a>



Registration #1	2007-06-01	20 mi
Registration #2	2010-05-06	54.642 mi
Registration #3	2011-04-13	71.022 mi
Registration #4	2012-01-23	77.994 mi
Registration #5	2012-01-24	77.994 mi
Registration #6	2013-01-26	92.199 mi
Registration #7	2013-01-28	92.199 mi
Registration #8	2014-01-17	101.800 mi
Registration #9	2015-01-26	114.783 mi
Registration #10	2016-01-25	122.026 mi
Registration #11	2016-01-25	122.026 mi
Registration #12	2016-01-25	122.026 mi
Registration #13	2016-01-25	122.026 mi
Registration #14	2016-01-25	122.026 mi
Registration #15	2016-01-25	122.026 mi
Registration #16	2016-01-25	122.026 mi
Registration #17	2016-01-25	122.026 mi
Registration #18	2016-01-25	122.026 mi
Registration #19	2016-01-25	122.026 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Kerb weight	1989 kg
Max. allowed weight	3200 kg

Additional information

Number of axles	2
Engine number	BNZ 030018