





General information

Make	CITROEN	
Model	C4 GRAND PICASSO HDI VTR PLUS	
Colour	Blue	
Year of manufacture	2015	
Top speed	112 mph	
0 - 60 mph	12.9 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	91 BHP
Max. torque	230 Nm at 2.000 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	104 g/km
CO2 label	В







Internet history

Entry 1

Date

Pictures

2021-06-28

16

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #10	2024-02-12 16:00	
MOT test number	916789889900	
Result	🗸 Passed	
Next expiry date	2025-02-11	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))		
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))		

MOT #9 2024-02-09 09:08 799290661742 **MOT test number** Result **X** Failed **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Advice Offside Rear Service brake binding but not excessively (1.2.1 (f)) Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Nearside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Fail Offside Rear Seat belt webbing significantly weakened 3rd row (7.1.2 (b) (ii))





MOT #8	2023-02-06 13:30
MOT test number	986691078145
Result	✓ Passed
 Advice Offside Front Inner Suspension arm pin or bush worn but not resulting rear bush (5.3.4 (a) (i)) Advice Nearside Front Inner Suspension arm pin or bush worn but not result rear bush (5.3.4 (a) (i)) 	
MOT #7	2022-02-08 12:18
MOT test number	975668744585
Result	✓ Passed
Advice Offside Rear Suspension arm pin or bush worn but not resulting in ex (5.3.4 (a) (i))	

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #6	2021-02-10 13:00	
MOT test number	202814768587	
Result	✓ Passed	
Advice Front Brake disc worn, but not excessively Slightly corroded with signs (1.1.14 (a) (i))	s of pitting on surfaces	
Advice Front Inner Tyre worn close to legal limit/worn on edge Both front tyres slightly worn on inner tread edges (5.2.3 (e))		
Minor Front Windscreen wiper blade defective Both front wipers slightly smea	ring (3.4 (b) (i))	

MOT #5	2020-01-29 13:43
MOT test number	308931326038
Result	✓ Passed
Advice Both front brake discs have corrosion on inner faces but pad	surface area still over 80%





MOT #4	2020-01-29 09:34	
MOT test number	534965503831	
Result	🗙 Failed	
Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))		
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Both front brake discs have corrosion on inner faces but pad surface area still over 80%		
Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))		
Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		

2019-01-25 09:34
234470952903
✓ Passed

MOT #2	2018-02-06 10:10
MOT test number	762960947734
Result	✓ Passed

MOT #1		2018-02-06 10:10
MOT test number		402425745834
Result		🗙 Failed
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)	



Tax & MOT check

Tax due: 1 July 2024	✓ Taxed	Expires: 11 February 2025	✓ МОТ
Tax status			Valid until 1 July
Days left			64
MOT expiry date			11 February 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		LAMP
Туре		
Damage 2		XAMPL
Date		
Category		SN61
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plata since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-24
Last registration	2024-02-12
Complete history	See info



Registration #1	2015-03-24	24 mi
Registration #2	2018-02-06	36.938 mi
Registration #3	2018-02-06	36.938 mi
Registration #4	2019-01-25	43.184 mi
Registration #5	2020-01-29	49.608 mi
Registration #6	2020-01-29	49.608 mi
Registration #7		11.777 mi
Registration #7 Registration #8		00.000 est
-		01.000 est 01.000 est 01.000 est
Registration #8		00.000 est 0.000 est 00.000 est 00.000 est
Registration #8 Registration #9		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est





Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1491 mm
Length	4329 mm
Wheel base	2608 mm
Kerb weight	1205 kg
Max. allowed weight	1790 kg
Additional information	
Additional information Fuel tank capacity	60 l
	60 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5