





General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Blue
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В







Internet history

Entry 2	
Date	2022-09-23
Pictures	11
Listing price	View report









source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-02-03 9

View report

source: autoonline.co.uk









MOT history

MOT expiry date	2025-02-01
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	11
Total items failed	7

MOT #12	2024-01-17 09:37
MOT test number	129293000767
Result	✓ Passed
Next expiry date	2025-02-01
Advice Offside Front Suspension arm pin or bush worn but not resulting in exercise (i))	cessive movement (5.3.4 (a)

MOT #11	2024-01-17 09:37
MOT test number	529276934700
Result	× Failed
Pass with rectification severely reduced (4.1.4 (b))	Nearside Front Headlamp has a product on the lens so that the light output is
Advice Offside Front Su (i))	spension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Pass with rectification all lamps (4.7.1 (b) (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or
Pass with rectification	Front Service brake excessively fluctuating (1.2.1 (e))

MOT #10	2023-02-02 09:06
MOT test number	958370842536
Result	✓ Passed





MOT #9	2022-06-24 12:22
MOT test number	808410318069
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MOT #8	2022-06-23 13:49
MOT test number	472693016828
Result	🗙 Failed
Fail Tyre has a tear, caused by separation or partial failure of its structure all (5.2.3 (d) (ii))	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7		2018-02-16 10:56
MOT test number		832001797526
Result		✓ Passed
Advice Front Brake pad(s)	wearing thin (3.5.1g)	
Advice Nearside Front whe	el bearing has slight play (2.5.A.3c))
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)		

MOT #6	2018-02-16 10:56	
MOT test number	820422063993	
Result	× Failed	
Pass with rectification	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice Front Brake pad(s) wearing thin (3.5.1g)		
Pass with rectification	Front Headlamp aim too low offside and nearside (1.8)	
Advice Nearside Front wheel bearing has slight play (2.5.A.3c)		
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)		





MOT #5	2017-02-18 16:14
MOT test number	728601662086
Result	✓ Passed
Result	V Passeu
Advice Tyre worn close to the legal limit Near side front (4.1.E.1)	
MOT #4	2015-08-04 15:15
MOT test number	145846515292
Result	✓ Passed
MOT #3	2014-05-01 11:19
MOT test number	777151824116
Result	✓ Passed
MOT #2	2013-04-29 14:55
MOT test number	269099213421
Result	✓ Passed
MOT #1	2012-05-08 15:43
MOT test number	126549822135
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 February 2025	✓ MOT Expires: 1 February 2025
Tax status	Valid until 1 February
Days left	279
MOT expiry date	1 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-03
Last registration	2024-01-17
Complete history	See info



Registration #1	2009-09-03	21 mi
Registration #2	2012-05-08	11.072 mi
Registration #3	2013-04-29	16.153 mi
Registration #4	2014-05-01	24.914 mi
Registration #5	2015-08-04	35.515 mi
Registration #6	2017-02-18	39.437 mi
Registration #7	2018-02-16	43.822 mi
Registration #8	2018-02-16	43.822 mi
Registration #9		11.777 mi
Registration #10		11.777 est
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462