



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Black
Year of manufacture	2013
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



**MOT history**

MOT expiry date	2024-09-06
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #8	2023-09-07 15:09
MOT test number	856627514312
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7	2022-08-25 13:47
MOT test number	220005564572
Result	✓ Passed
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Minor	Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))

MOT #6	2020-11-20 10:11
MOT test number	854306248411
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2019-06-18 08:35**MOT test number** 894304493091**Result** ✓ Passed**MOT #4** 2018-08-10 10:16**MOT test number** 125947693488**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 3mm (5.2.3 (e))**Advice** Both front tyres wearing on the inner and outer shoulders**Advice** Offside Front Tyre worn close to legal limit/worn on edge On 3mm (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #3** 2018-08-10 10:16**MOT test number** 962991654973**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 3mm (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Both front tyres wearing on the inner and outer shoulders**Advice** Offside Front Tyre worn close to legal limit/worn on edge On 3mm (5.2.3 (e))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #2** 2017-08-11 09:51**MOT test number** 896149326318**Result** ✓ Passed**MOT #1** 2016-08-11 13:53**MOT test number** 693723842392**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-03-28
Current registration	 
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2013-08-13
Last registration	2023-09-07
Complete history	See info



Registration #1	2013-08-13	29 mi
Registration #2	2016-08-11	7.713 mi
Registration #3	2017-08-11	15.994 mi
Registration #4	2018-08-10	29.246 mi
Registration #5	2018-08-10	29.246 mi
Registration #6	2019-08-09	29.246 mi
Registration #7	2019-08-09	29.246 mi
Registration #8	2019-08-09	29.246 mi
Registration #9	2023-09-07	29.246 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HACU594011