





report date: 2024-03-28

## General information

| Make                | MINI                 |
|---------------------|----------------------|
| Model               | COUNTRYMAN COOPER SD |
| Colour              | Black                |
| Year of manufacture | 2014                 |
| Top speed           | 123 mph              |
| 0 - 60 mph          | 9.3 seconds          |
| Gearbox             | 6 speed Manual       |

## Engine & fuel consumption

| Power                   | 143 BHP             |
|-------------------------|---------------------|
| Max. torque             | 305 Nm at 1.750 rpm |
| Engine capacity         | 1.995 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 54.3 mpg            |
| Consumption extra urban | 65.7 mpg            |
| Consumption combined    | 61.4 mpg            |
| CO2 emission            | 122 g/km            |
| CO2 label               | D                   |



CarCheck.co.uk page 1/10



report date: 2024-03-28

| B 4   | $\sim$ $-$ |     |     |      |
|-------|------------|-----|-----|------|
| 10.71 | $\alpha$   | - h | sto | rv   |
| 101   | ( ) I      |     | 510 | II V |
|       | •          |     |     | . ,  |

| MOT expiry date    | 2024-06-25 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 2          |
| Total advice items | 12         |
| Total items failed | 5          |

| MOT #8           | 2023-06-20 11:24 |
|------------------|------------------|
| MOT test number  | 779299231117     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-06-25       |

| MOT #7          | 2022-06-15 08:48 |
|-----------------|------------------|
| MOT test number | 218344411228     |
| Result          | <b>√</b> Passed  |

| MOT #6          | 2021-06-11 08:14 |
|-----------------|------------------|
| MOT test number | 804616047004     |
| Result          | <b>✓</b> Passed  |

| MOT #5 | 2020-06-26 11:15 |
|--------|------------------|

**MOT test number** 300242638345

| Result | ✓ Passed   |
|--------|--|
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii))      |
| Advice | Offside Front Suspension component pin or bush slightly worn strut top worn (5.3.4 (a) (i))  |
| Advice | Offside Front Valve stem slightly damaged (5.2.3 (j))  |
| Advice | Nearside Front Suspension component pin or bush slightly worn strut top worn (5.3.4 (a) (i)) |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt                   |

CarCheck.co.uk page 2/10



report date: 2024-03-28

**MOT #4** 2020-06-26 11:15 **MOT** test number 159228429967 Result × Failed **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Offside Front Valve stem slightly damaged (5.2.3 (j)) Offside Front Suspension component pin or bush slightly worn strut top worn (5.3.4 (a) (i)) **Advice** Nearside Front Suspension component pin or bush slightly worn strut top worn (5.3.4 (a) (i)) Advice **Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii)) Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #3

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT** #2 2019-04-02 09:32 **MOT** test number 784144607388 Result × Failed **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Nearside Headlamp aim too low (4.1.2 (a))

MOT #1 2017-04-18 14:22

MOT test number 805377397339

Result ✓ Passed

CarCheck.co.uk page 3/10



PE14TWD
report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 December |
|------------------|------------------------|
| Days left        | 216                    |
| MOT expiry date  | 25 June 2024           |
| Full MOT history | See MOT history        |

#### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Venicle class                           | 43         |
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 4/10



PE14TWD report date: 2024-03-28

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



PE14TWD report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Plate since

PE14TWD

report date: 2024-03-28

More info >

| Owner history  |           |       |
|--|-----------|-------|
| For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report he |           | e?    |
| *********  |           |       |
| ***************************************  |           |       |
| *************  |           |       |
| *********  |           |       |
| ***************************************  |           |       |
| ***************************************  |           |       |
|  | More info | >     |
| Plate changes  |           |       |
| See in this check if this MINI had different number plates.  |           |       |
| Number of plates   |           |       |
| Current registration   | NE UK     |       |
| Plate since  |           | n.n.n |
| Current registration   |           |       |

CarCheck.co.uk page 7/10



report date: 2024-03-28

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 8/10



report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 9          |
| First mileage registration | 2014-03-31 |
| Last registration          | 2023-06-20 |
| Complete history           | See info   |



| Registration #1 | 2014-03-31 | 14 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2017-04-18 | 36.775 mi |
| Registration #3 | 2019-04-02 | 48.539 mi |
| Registration #4 | 2019-04-02 | 48.539 mi |
| Registration #5 | 2020-06-26 | 54.794 mi |
| Registration #6 |            | 71.777 66 |
| Registration #7 |            | 11.777 es |
| Registration #8 |            | 11.777 es |
| Registration #9 |            | 11.777 au |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

# Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 60482 |                  |
| 0501  |                  |
| 0566  |                  |
| 0567  |                  |
| 60569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 84%             |
| Children       | 83%             |
| Pedestrian     | 63%             |
| Safety systems | 71%             |
| Overall rating | 78%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1789 mm |
|---------------------|---------|
| Height              | 1561 mm |
| Length              | 4110 mm |
| Wheel base          | 2595 mm |
| Kerb weight         | 1320 kg |
| Max. allowed weight | 1830 kg |

## Additional information

| Fuel tank capacity                | 47 I             |            |
|-----------------------------------|------------------|------------|
| Fuel delivery                     | Direct Injection |            |
| Number of doors                   | 5                |            |
| Number of seats<br>CarCheck.co.uk | 5                | page 10/10 |