



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V I-VTEC EX
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	174 Nm at 4.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-05
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT #18	2021-07-10 14:15
MOT test number	853939318519
Result	✓ Passed
Next expiry date	2022-07-09
Advice	Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

MOT #17	2021-07-10 14:15
MOT test number	727044195755
Result	✗ Failed
Pass with rectification	Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

MOT #16	2020-12-03 09:41
MOT test number	389150984399
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #15	2020-12-03 09:41
MOT test number	615230937064
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Vehicles internal headlight adjuster altered to recheck lights
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))

**MOT #14**

2019-12-19 11:52

**MOT test number**

824734637521

**Result**

✓ Passed

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Coolant leak**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #13**

2018-12-18 17:00

**MOT test number**

872596619380

**Result**

✓ Passed

**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2018-12-18 09:37

**MOT test number**

940407575209

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #11** 2017-12-21 10:17**MOT test number** 345562357770**Result** ✓ Passed**MOT #10** 2016-12-22 16:56**MOT test number** 547103623614**Result** ✓ Passed**MOT #9** 2016-12-22 10:38**MOT test number** 314473427270**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage insecure (2.4.G.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2015-12-21 10:42**MOT test number** 518874437319**Result** ✓ Passed**MOT #7** 2014-12-22 13:07**MOT test number** 407346054401**Result** ✓ Passed**Advice** Offside Inner Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Inner Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-12-10 15:01**MOT test number** 548144043388**Result** ✓ Passed**Notice** Oil leak

**MOT #5** 2013-12-10 10:57**MOT test number** 959594443323**Result** ✗ Failed**Notice** Oil leak**Fail** Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2013-01-22 16:05**MOT test number** 466932923095**Result** ✓ Passed**MOT #3** 2012-03-15 11:53**MOT test number** 498235372092**Result** ✓ Passed**Notice** Oil leak**MOT #2** 2011-03-10 11:45**MOT test number** 165849861060**Result** ✓ Passed**MOT #1** 2010-03-18 10:33**MOT test number** 911527270042**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-27
Last registration	2021-07-10
Complete history	<a href="#">See info</a>



Registration #1	2007-03-27	8 mi
Registration #2	2010-03-18	43.028 mi
Registration #3	2011-03-10	60.448 mi
Registration #4	2012-03-15	76.350 mi
Registration #5	2013-01-22	81.446 mi
Registration #6	2013-12-10	88.172 mi
Registration #7	2013-12-10	88.172 mi
Registration #8	2014-12-22	95.720 mi
Registration #9	2015-12-21	103.081 mi
Registration #10	2016-12-22	110.484 mi
Registration #11	2016-12-22	110.484 mi
Registration #12	2016-12-22	110.484 mi
Registration #13	2016-12-22	110.484 mi
Registration #14	2016-12-22	110.484 mi
Registration #15	2016-12-22	110.484 mi
Registration #16	2016-12-22	110.484 mi
Registration #17	2016-12-22	110.484 mi
Registration #18	2016-12-22	110.484 mi
Registration #19	2016-12-22	110.484 mi
Registration #20	2016-12-22	110.484 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1625 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1449 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	R18A11308117