





report date: 2024-03-29

General information

| Make | MINI | |
|---------------------|----------------------------|--|
| Model | COUNTRYMAN COOPER S E ALL4 | |
| Colour | Black | |
| Year of manufacture | 2017 | |
| Top speed | 123 mph | |
| 0 - 60 mph | 6.8 seconds | |
| Gearbox | 6 speed automatic | |

Engine & fuel consumption

| Power | 221 BHP |
|----------------------|---------------------|
| Max. torque | 385 Nm at 1.350 rpm |
| Engine capacity | 1.499 сс |
| Cylinders | 3 |
| Fuel type | Hybrid / Electric |
| Consumption combined | 134.5 mpg |
| CO2 emission | 49 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/10



NL67CZO

report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/10



MOT history

NL67CZO report date: 2024-03-29

| , | |
|--------------------|------------|
| MOT expiry date | 2025-04-12 |
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #5 | 2024-04-06 11:42 |
|------------------|------------------|
| MOT test number | 215988432136 |
| Result | √ Passed |
| Next expiry date | 2025-04-12 |

| MOT #4 | 2023-03-20 11:13 |
|--|------------------|
| MOT test number | 696746562027 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #3 | 2022-04-02 14:14 |
|--|------------------|
| MOT test number | 944897608883 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #2 | 2021-04-13 14:49 |
|-----------------|------------------|
| MOT test number | 696984131256 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-09-19 08:42 |
| MOT test number | 758706103849 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 12 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 59 |
|-------------------------------|------------|
| Band | В |
| First licence fee (12 months) | £ 0,00,- |
| Standard rate (12 months) | £ 170,00,- |
| Standard rate (6 months) | £ 93,50,- |
| Premium rate (12 months) | £ 560,00,- |
| Premium rate (6 months) | £ 308,00,- |

CarCheck.co.uk page 4/10



NL67CZO

report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



faste since

NL67CZO

report date: 2024-03-29

More info >

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MINI had different number plates.

CarCheck.co.uk page 7/10



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2017-10-10 |
| Last registration | 2024-04-06 |
| Complete history | See info |



| Registration #1 | 2017-10-10 | 11 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-09-19 | 31.509 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | 2021-04-13 | 32.774 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



NL67CZO

report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 80% |
| Pedestrian | 64% |
| Safety systems | 51% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| Width | 1822 mm |
|---------------------|---------|
| Height | 1557 mm |
| Length | 4299 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1735 kg |
| Max. allowed weight | 2270 kg |

Additional information

| Fuel tank capacity | 36 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 10/ |

Number of axles 2

Engine number F288H583