



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D5 SE LUX
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-07-03
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-09
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-10
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	22
Total items failed	12

MOT #20	2024-01-11 17:14
MOT test number	466805148444
Result	✓ Passed
Next expiry date	2025-01-10
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #19	2022-11-09 13:30
MOT test number	242925933373
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18** 2021-09-02 12:45**MOT test number** 981815789464**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**MOT #17** 2021-08-27 10:51**MOT test number** 740763815708**Result** ✗ Failed**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Play in steering rack inner joint(s)**Fail** Nearside Front Outer Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2020-08-01 06:34**MOT test number** 131366689865**Result** ✓ Passed**MOT #15** 2019-07-30 08:53**MOT test number** 646890574667**Result** ✓ Passed**MOT #14** 2018-08-06 09:51**MOT test number** 278291201994**Result** ✓ Passed

**MOT #13** 2017-08-10 13:08**MOT test number** 356326877566**Result** ✓ Passed**MOT #12** 2016-01-28 09:58**MOT test number** 481648666021**Result** ✓ Passed**MOT #11** 2015-01-30 15:18**MOT test number** 169700435487**Result** ✓ Passed**MOT #10** 2015-01-30 15:18**MOT test number** 605960235048**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2013-12-12 13:11**MOT test number** 106236243344**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #8** 2013-12-12 10:28**MOT test number** 398816143320**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #7** 2012-11-20 16:31**MOT test number** 497325322456**Result** ✓ Passed**Notice** Both rear tyres worn on the inner edges.**MOT #6** 2012-11-20 16:31**MOT test number** 157395922375**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Both rear tyres worn on the inner edges.**MOT #5** 2012-01-04 16:50**MOT test number** 329084702034**Result** ✓ Passed**MOT #4** 2012-01-03 13:12**MOT test number** 156573502486**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-12-03 15:19**MOT test number** 163727430337**Result** ✓ Passed

**MOT #2**

2010-12-03 11:19

MOT test number

422097830490

Result**✗ Failed****Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #1**

2010-06-14 11:31

MOT test number

130305060110

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 January 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BX07DCZ
Plate since	2024-03-29
Current registration	BX07DCZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-01
Last registration	2024-01-11
Complete history	See info



Registration #1	2007-03-01	22 mi
Registration #2	2010-06-14	52.591 mi
Registration #3	2010-12-03	58.872 mi
Registration #4	2010-12-03	58.872 mi
Registration #5	2012-01-03	69.484 mi
Registration #6	2012-01-04	69.484 mi
Registration #7	2012-11-20	77.874 mi
Registration #8	2013-12-12	90.382 mi
Registration #9	2013-12-12	90.382 mi
Registration #10	2015-01-30	98.564 mi
Registration #11	2016-01-28	99.781 mi
Registration #12	2016-01-28	99.781 mi
Registration #13	2016-01-28	99.781 mi
Registration #14	2016-01-28	99.781 mi
Registration #15	2016-01-28	99.781 mi
Registration #16	2016-01-28	99.781 mi
Registration #17	2016-01-28	99.781 mi
Registration #18	2016-01-28	99.781 mi
Registration #19	2016-01-28	99.781 mi
Registration #20	2016-01-28	99.781 mi
Registration #21	2016-01-28	99.781 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1861 kg
Max. allowed weight	2390 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	545484