



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN SPORT TDI 4MOTION
Colour	Grey
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-06-19
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-02
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	42
Total items failed	7

MOT #17	2023-06-03 10:58
MOT test number	329501366289
Result	✓ Passed
Next expiry date	2024-06-02

MOT #16	2022-05-23 08:53
MOT test number	481616270812
Result	✓ Passed

MOT #15	2021-05-27 13:47
MOT test number	868466276711
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear oil leaks but not excessive
Advice	Rear Coil spring corroded both side (5.3.1 (b) (i))

**MOT #14**

2020-07-21 11:01

MOT test number

539037008373

Result

✓ Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13**

2019-03-14 16:06

MOT test number

599908153250

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Fluid leak, but not excessive Rear diff leaking (8.4.1 (a) (i))**Advice** Nearside Rear Bump stop damaged**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12**

2017-06-02 11:25

MOT test number

691804915296

Result

✓ Passed

- Advice** Rear exhaust clamp broken not blowing
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Both front console bushes deteriorating
- Advice** N/S/R bump stop damaged
- Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** N/S/R tyre perishing
- Advice** Rear diff leaking
- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #11

2016-06-10 09:04

MOT test number

483730029905

Result

✓ Passed

- Advice** Offside Rear Inner brake light not working
- Advice** Offside Rear Inner position lamp inop
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear diff oil leak

**MOT #10** 2016-06-03 14:15**MOT test number** 588775749666**Result** ✗ Failed**Advice** Rear diff oil leak**Fail** Offside Side repeater not working (1.4.A.2c)**Advice** Offside Rear Inner brake light not working**Advice** Offside Rear Inner position lamp inop**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2015-06-08 13:20**MOT test number** 768909655177**Result** ✓ Passed**MOT #8** 2015-06-08 13:20**MOT test number** 129959355181**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2014-05-28 17:10**MOT test number** 467468744112**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-06-13 13:35**MOT test number** 226664463180**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2013-06-12 15:43**MOT test number** 345713663187**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Offside Inner Rear position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Inner Rear position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-05-10 10:05**MOT test number** 915581832189**Result** ✓ Passed



MOT #3	2012-05-10 10:05
MOT test number	727131432163
Result	✗ Failed
Pass with rectification	Offside Rear Rear position lamp(s) not working (1.1.A.3b)

MOT #2	2011-05-09 09:40
MOT test number	865049321105
Result	✓ Passed

MOT #1	2011-05-06 14:22
MOT test number	936326121199
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
2 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ML08LVU
Plate since	2019-09-29
Current registration	 ML08LVU
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-08
Last registration	2023-06-03
Complete history	See info



Registration #1	2008-05-08	27 mi
Registration #2	2011-05-06	57.639 mi
Registration #3	2011-05-09	57.639 mi
Registration #4	2012-05-10	66.704 mi
Registration #5	2013-06-12	74.256 mi
Registration #6	2013-06-13	74.275 mi
Registration #7	2014-05-28	79.006 mi
Registration #8	2015-06-08	85.864 mi
Registration #9	2016-06-03	93.717 mi
Registration #10	2016-06-03	93.717 mi
Registration #11	2016-06-03	93.717 mi
Registration #12	2016-06-03	93.717 mi
Registration #13	2016-06-03	93.717 mi
Registration #14	2016-06-03	93.717 mi
Registration #15	2016-06-03	93.717 mi
Registration #16	2016-06-03	93.717 mi
Registration #17	2016-06-03	93.717 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CBA 010785