



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-03
Pictures	28
Listing price	View report



source: theaa.com



MOT history

MOT expiry date	2024-06-01
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	28
Total items failed	14

MOT #13	2023-05-12 13:33
---------	------------------

MOT test number	572578244048
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-01
------------------	------------

Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front brake shield corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2023-05-11 12:52

MOT test number

964714221705

Result**✗ Failed****Fail** Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Windscreen washer not working (3.5 (a))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front brake shield corroded**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2022-05-26 15:30

MOT test number

234397492692

Result**✓ Passed**

**MOT #10**

2022-05-24 14:13

MOT test number

234121865570

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, but not excessively very poor (1.1.14 (a) (i))**Fail** Brake performance not tested due to suspension ball joint (1.2.1 (g))**MOT #9**

2021-06-02 16:00

MOT test number

854892487113

Result**✓ Passed****Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (5.1.2 (b) (i))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (5.1.2 (b) (i))**MOT #8**

2021-06-01 15:00

MOT test number

126718629385

Result**✗ Failed****Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (5.1.2 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn trailing arm bush (5.1.2 (b) (i))

**MOT #7**

2020-08-10 10:05

MOT test number

493354414104

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 235/50/19v (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge 235/50/19v (5.2.3 (e))

MOT #6

2020-08-06 14:27

MOT test number

517796786699

Result

✗ Failed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 235/50/19v (5.2.3 (e))

Fail

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge 235/50/19v (5.2.3 (e))

Fail

Nearside Inner Steering rack gaiter missing or no longer prevents the ingress of dirt clip missing (2.1.3 (g) (ii))

MOT #5

2019-08-06 13:57

MOT test number

102273231681

Result

✓ Passed

MOT #4

2018-08-02 15:59

MOT test number

675108769498

Result

✓ Passed

Advice

Nearside Rear Nail in tyre

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #3	2017-08-03 10:11
MOT test number	307784243804
Result	✓ Passed
MOT #2	2016-08-05 10:46
MOT test number	697862036153
Result	✓ Passed
MOT #1	2015-08-11 12:43
MOT test number	205423725268
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-18
Last registration	2023-05-12
Complete history	See info



Registration #1	2013-03-18	17 mi
Registration #2	2015-08-11	10.237 mi
Registration #3	2016-08-05	19.393 mi
Registration #4	2017-08-03	28.063 mi
Registration #5	2018-08-02	36.540 mi
Registration #6	2019-08-06	47.793 mi
Registration #7	2020-08-06	56.241 mi
Registration #8	2020-08-10	56.257 mi
Registration #9	2020-08-10	56.257 mi
Registration #10	2020-08-10	56.257 mi
Registration #11	2020-08-10	56.257 mi
Registration #12	2020-08-10	56.257 mi
Registration #13	2020-08-10	56.257 mi
Registration #14	2020-08-10	56.257 mi
Registration #15	2020-08-10	56.257 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ