





report date: 2024-03-29

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | IX20 PREMIUM |
| Colour | Silver |
| Year of manufacture | 2016 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 123 BHP |
|-------------------------|---------------------|
| Max. torque | 156 Nm at 4.200 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 150 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2022-01-13

Pictures 34

Listing price View report









source: cargurus.co.uk

Entry 1


| Date | 2022-01-06 |
|----------|------------|
| Pictures | 35 |

Listing price View report









source: autotrader.co.uk

CarCheck.co.uk page 2/11



GX66LWH report date: 2024-03-29

2023-04-11 14:41

MOT history

MOT #6

| MOT expiry date | 2025-04-16 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 1 |
| Total items failed | 4 |

| MOT #8 | 2024-04-17 11:50 |
|------------------|------------------|
| MOT test number | 392839840239 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-16 |

| MOT #7 | 2024-04-05 07:49 |
|--|------------------|
| MOT test number | 733520552574 |
| Result | 🗙 Failed |
| Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a)) | |
| Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) | |

| MOT test number | 560167899072 |
|--|-------------------------------------|
| Result | ✓ Passed |
| Advice Nearside Rear Parking brake efficiency only just met. It w requires adjustment or repair. (1.4.2 (a) (i)) | ould appear that the braking system |

| MOT #5 | 2022-04-07 09:37 |
|-----------------|------------------|
| MOT test number | 672853817151 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

| MOT #4 | 2021-03-17 14:51 |
|--|------------------|
| MOT test number | 426030500066 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2021-03-17 13:47 |
| MOT test number | 538839385903 |
| Result | × Failed |
| Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |

| Fail Front Windscreen wiper does not clear the windscreen effectively (3.4) | 4 (b) (ii)) |
|---|------------------|
| MOT #2 | 2020-03-18 16:51 |
| MOT test number | 146559807056 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2019-07-09 13:37 |
| MOT test number | 872633398812 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



GX66LWH report date: 2024-03-29

Tax & MOT check

Tax expired: 22 July 2023





Expires: 16 April 2025

| Tax status | Expired at 22 July 2023 |
|------------------|-------------------------|
| Days left | 282 days too late |
| MOT expiry date | 16 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Venicle class | 40 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| , , | |
|--|------------------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| ******** | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | NK NE |
| Plate since | |
| Current registration | NIK ZIK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2016-09-27 |
| Last registration | 2024-04-17 |
| Complete history | See info |



| Registration #1 | 2016-09-27 | 8 mi |
|------------------|------------|-----------|
| Registration #2 | 2019-07-09 | 8.250 mi |
| Registration #3 | 2020-03-18 | 9.338 mi |
| Registration #4 | 2021-03-17 | 12.407 mi |
| Registration #5 | 2021-03-17 | 12.407 mi |
| Registration #6 | | 0.00 44 |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 0.00 44 |
| Registration #11 | | 10.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|---------------------|---------|
| Height | 1600 mm |
| Length | 4120 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1335 kg |
| Max. allowed weight | 1780 kg |

Additional information

| Fuel tank capacity | 50 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number G4FCGZ637846