




report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-07-20
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-17
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	44
Total items failed	0

MOT #122023-08-16 10:23

MOT test number137515531704

Result✓ Passed

Next expiry date2024-08-17

- Advice** Rear Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))
- Advice** Front Inner Tyre worn close to legal limit/worn on edge inner shoulders of both n/s and o/s (5.2.3 (e))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Suspension arm corroded but not seriously weakened both n/s and o/s (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2023-08-15 12:31

MOT test number

283395496119

Result**✗ Failed**

- Advice** Rear Suspension arm corroded but not seriously weakened both n/s and o/s (5.3.3 (b) (i))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))
- Advice** Front Inner Tyre worn close to legal limit/worn on edge inner shoulders of both n/s and o/s (5.2.3 (e))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10

2022-08-18 12:04

MOT test number

311732140875

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Suspension arm corroded but not seriously weakened n/s and o/s arms corroded (5.3.3 (b) (i))

MOT #9

2021-08-05 10:46

MOT test number

569875860714

Result**✓ Passed**



MOT #82021-03-09 13:17

MOT test number988685147158

Result		✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))	

**MOT #7**

2021-02-24 17:32

MOT test number

225615163049

Result**✗ Failed**

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also smooth on inner (5.2.3 (d) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

MAJOR Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Reversing lamp inoperative (4.6.1 (a))

MAJOR Rear Registration plate missing (0.1 (a))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MAJOR Front Registration plate missing (0.1 (a))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #6

2019-09-19 09:23

MOT test number

276143895568

Result**✓ Passed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #5** 2018-09-13 11:27**MOT test number** 160105996324**Result** ✓ Passed**MOT #4** 2018-09-12 11:11**MOT test number** 828933285510**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Front Registration plate inscription illegible (0.1 (b))**MOT #3** 2017-09-21 12:56**MOT test number** 537476268262**Result** ✓ Passed**MOT #2** 2016-09-23 15:23**MOT test number** 560833605439**Result** ✓ Passed**MOT #1** 2015-09-17 09:54**MOT test number** 266363701693**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	MA62AWR
Plate since	2019-03-29
Current registration	MA62AWR
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-20
Last registration	2023-08-16
Complete history	See info



Registration #1	2012-09-20	12 mi
Registration #2	2015-09-17	33.032 mi
Registration #3	2016-09-23	41.153 mi
Registration #4	2017-09-21	48.540 mi
Registration #5	2018-09-12	57.492 mi
Registration #6	2018-09-13	57.496 mi
Registration #7	2019-09-19	67.765 mi
Registration #8	2019-09-20	67.765 mi
Registration #9	2019-09-20	67.765 mi
Registration #10	2019-09-20	67.765 mi
Registration #11	2019-09-20	67.765 mi
Registration #12	2019-09-20	67.765 mi
Registration #13	2019-09-20	67.765 mi
Registration #14	2019-09-20	67.765 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	145854K