



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D5 SE
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-04
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT #16	2021-04-06 14:07
MOT test number	497079371685
Result	✓ Passed
Next expiry date	2022-04-05

**MOT #15**

2021-03-05 14:47

**MOT test number**

528948934413

**Result****✗ Failed**

- Fail** Steering lock stop missing (2.1.4 (b))
- Fail** Nearside Front Steering lock stop missing (2.1.4 (b))
- Fail** Nearside Front Tyre fouling a part of the vehicle missing steering stop (5.2.3 (f))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Nail in tyre
- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Advice** Exhaust mounting defective (6.1.2 (a))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Front Tyre fouling a part of the vehicle severely deteriorated steering stop (5.2.3 (f))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Brake fluid contaminated (1.8 (a))

**MOT #14** 2020-03-10 13:08**MOT test number** 228191935693**Result** ✓ Passed**MOT #13** 2020-03-10 09:01**MOT test number** 777509142420**Result** ✗ Failed

- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #12** 2020-03-04 14:29**MOT test number** 627472931935**Result** ✗ Failed

- Fail** Front Tyre fouling a part of the vehicle both sides (5.2.3 (f))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear Exhaust mounting defective broken from weld, supported by wire (6.1.2 (a))
- Fail** Front Steering lock stop missing both missing due to excessive ware (2.1.4 (b))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/50/17/98w (5.2.3 (d) (i))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #11** 2019-02-23 07:43**MOT test number** 896948568366**Result** ✓ Passed

**MOT #10** 2019-02-22 08:30**MOT test number** 365967787255**Result** ✗ Failed

- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9** 2018-01-08 11:35**MOT test number** 858292652283**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-12-10 07:42**MOT test number** 980442343177**Result** ✓ Passed**MOT #7** 2015-01-13 11:40**MOT test number** 627533115078**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2014-01-08 13:11**MOT test number** 699028004093**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-01-14 09:36**MOT test number** 137444813038**Result** ✓ Passed**MOT #4** 2012-01-09 13:08**MOT test number** 379029202028**Result** ✓ Passed**MOT #3** 2011-01-15 10:21**MOT test number** 279955711039**Result** ✓ Passed**MOT #2** 2009-08-24 11:47**MOT test number** 541586139257**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-09-06 08:58**MOT test number** 751440558294**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 OY55TZK
Plate since	2019-03-29
Current registration	 OY55TZK
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-09-12
Last registration	2021-04-06
Complete history	<a href="#">See info</a>



Registration #1	2005-09-12	25 mi
Registration #2	2008-09-06	31.218 mi
Registration #3	2009-08-24	47.672 mi
Registration #4	2011-01-15	69.580 mi
Registration #5	2012-01-09	77.789 mi
Registration #6	2013-01-14	97.772 mi
Registration #7	2014-01-08	114.583 mi
Registration #8	2015-01-13	126.038 mi
Registration #9	2016-12-10	129.374 mi
Registration #10	2019-05-20	151.377 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi
Registration #18	2019-05-20	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1830 mm
Height	1430 mm
Length	4820 mm
Wheel base	2790 mm
Kerb weight	1465 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	266815
---------------	--------