



report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-27
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-01
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	38
Total items failed	18

MOT #20	2023-08-02 15:18
---------	------------------

MOT test number	854652442576
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-01
------------------	------------

Advice	Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Items removed from driver's view prior to test
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords and perished (5.2.3 (d) (i))

**MOT #19**

2023-08-02 08:21

MOT test number

376975980134

Result**✗ Failed**

- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Rear Shock absorbers has a serious fluid leak shock corroded (5.3.2 (b))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords and perished (5.2.3 (d) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #18

2022-07-18 09:40

MOT test number

767212020841

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

**MOT #17**

2022-07-18 09:40

MOT test number

737573106580

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16

2021-08-02 15:30

MOT test number

181353002308

Result**✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15

2021-08-02 10:42

MOT test number

452559562430

Result**✗ Failed**

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14** 2019-09-09 16:00**MOT test number** 447153329015**Result** ✓ Passed**MOT #13** 2019-09-09 12:28**MOT test number** 580079378430**Result** ✗ Failed

Fail Nearside Front Suspension component attachment bracket/mounting insecure and impairing directional stability top mount (5.3.3 (a) (ii))

Fail Offside Front Suspension component attachment bracket/mounting insecure and impairing directional stability top mount (5.3.3 (a) (ii))

MOT #12 2018-09-10 15:30**MOT test number** 700777641238**Result** ✓ Passed

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2018-09-10 09:44**MOT test number** 504576707276**Result** ✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Front Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))

MOT #10 2017-09-20 11:26**MOT test number** 780754709278**Result** ✓ Passed

**MOT #9** 2017-09-20 07:57**MOT test number** 666570278258**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear fog lamp emits a light other than red (1.3.2e)**MOT #8** 2017-06-09 15:50**MOT test number** 676236241371**Result** ✓ Passed**MOT #7** 2017-06-09 13:59**MOT test number** 613336554125**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm x2 (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2016-06-03 12:27**MOT test number** 360375762216**Result** ✓ Passed**Advice** Offside Front tyre m/s fitted**MOT #5** 2015-06-08 11:21**MOT test number** 268579155497**Result** ✓ Passed**MOT #4** 2014-06-11 11:55**MOT test number** 688452164118**Result** ✓ Passed



MOT #3	2013-10-29 13:26
MOT test number	835742503331
Result	✓ Passed

MOT #2	2013-10-29 11:02
MOT test number	526132803363
Result	✗ Failed
<div><div>Fail</div>Nearside Front Tyre has ply or cords exposed (4.1.D.1b)</div>	
<div><div>Fail</div>Windscreen washer provides insufficient washer liquid (8.2.3)</div>	
<div><div>Fail</div>Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)</div>	
<div><div>Fail</div>Offside Front Tyre has ply or cords exposed (4.1.D.1b)</div>	
<div><div>Fail</div>Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)</div>	

MOT #1	2012-10-24 11:43
MOT test number	665878392217
Result	✓ Passed
<div><div>Advice</div>Nearside Front Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-10-28
Last registration	2023-08-02
Complete history	See info



Registration #1	2009-10-28	25 mi
Registration #2	2012-10-24	26.658 mi
Registration #3	2013-10-29	35.184 mi
Registration #4	2013-10-29	35.184 mi
Registration #5	2014-06-11	38.713 mi
Registration #6	2015-06-08	44.862 mi
Registration #7	2016-06-03	50.853 mi
Registration #8	2017-06-09	60.588 mi
Registration #9	2017-06-09	60.588 mi
Registration #10	2017-09-20	63.844 mi
Registration #11	2017-09-20	63.845 mi
Registration #12	2018-06-09	66.588 mi
Registration #13	2018-06-09	66.588 mi
Registration #14	2018-06-09	66.588 mi
Registration #15	2018-06-09	66.588 mi
Registration #16	2018-06-09	66.588 mi
Registration #17	2018-06-09	66.588 mi
Registration #18	2018-06-09	66.588 mi
Registration #19	2018-06-09	66.588 mi
Registration #20	2018-06-09	66.588 mi
Registration #21	2018-06-09	66.588 mi
Registration #22	2018-06-09	66.588 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9569037