





General information

| Make | HYUNDAI |
|---------------------|----------------------------|
| Model | I40 CRDI SE NAV BLUE DRIVE |
| Colour | Blue |
| Year of manufacture | 2017 |
| Top speed | 124 mph |
| Gearbox | 7 speed Semi-Automatic |

Engine & fuel consumption

| Power | 139 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 1.700 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |



HV67EHD report date: 2024-03-28

Internet history

| Entry | 2 |
|-------|---|
| | |

Date Pictures 2021-10-20

33

Listing price

View report



source: autotrader.co.uk

Entry 1

Date

Pictures

Listing price

3

2021-10-12

View report



source: cargurus.co.uk







MOT history

| MOT expiry date | 2024-10-03 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 0 |

| MOT #5 | 2023-10-04 12:34 |
|------------------|------------------|
| MOT test number | 241345785256 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-03 |

| МОТ #4 | 2022-09-14 12:57 |
|-----------------|------------------|
| MOT test number | 307345580782 |
| Result | ✓ Passed |

| MOT #3 | | 2021-08-27 09:48 |
|----------|---|------------------|
| MOT test | number | 406818696275 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2. | 3 (d) (i)) |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5. | 2.3 (d) (i)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #2 | 2020-08-17 14:54 |
|--|------------------|
| MOT test number | 526071605437 |
| Result | 🗸 Passed |
| Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |





| MOT #1 | 2020-08-17 09:17 |
|--|------------------|
| MOT test number | 400552528472 |
| Result | 🗙 Failed |
| DANGEROUS Nearside Front Inner Tyre has a tear, caused by separation or part (5.2.3 (d) (ii)) Minor Central Windscreen damaged but not adversely affecting driver's view (3) | |
| Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e |)) |
| | |



Tax & MOT check

| √ Taxed | √ МОТ |
|----------------------------|----------------------------|
| Tax due: 1 October 2024 | Expires: 3 October 2024 |
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 3 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| - |
|-----|
| AMP |
| |
| |
| - A |
| |
| |
| |
| |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

| and the second se | |
|---|-------------|
| ********* | |
| ******* | |
| ****** | |
| ********* | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2017-09-13 |
| Last registration | 2023-10-04 |
| Complete history | See info |



| Registration #1 | 2017-09-13 | 19 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-08-17 | 31.110 mi |
| Registration #3 | 2020-08-17 | 31.126 mi |
| Registration #4 | 2021-08-27 | 41.512 mi |
| Registration #5 | | 11.177 esi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 10.000 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 86% |
| Pedestrian | 43% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1815 mm |
| Height | 1470 mm |
| Length | 4775 mm |
| Wheel base | 2770 mm |
| Kerb weight | 1659 kg |
| Max. allowed weight | 2150 kg |
| Additional information | |
| Fuel tank capacity | 70 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Engine number

2

D4FDHU743820