



SAI5YLB

report date: 2024-03-28

General information

Make	MINI
Model	ROADSTER ONE
Colour	White
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	49.6 mpg







Internet history

Entry 3



Date	2021-07-04
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-06-29
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-26
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

**MOT history****MOT #8** 2022-07-22 15:19**MOT test number** 636493999985**Result** ✓ Passed**Next expiry date** 2023-07-21**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement leaking (5.3.4 (a) (i))**MOT #7** 2022-07-19 08:57**MOT test number** 950147259365**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement leaking (5.3.4 (a) (i))**MOT #6** 2021-07-06 11:03**MOT test number** 302317959869**Result** ✓ Passed**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #5** 2020-10-28 13:45**MOT test number** 143396234133**Result** ✓ Passed**MOT #4** 2019-05-10 12:52**MOT test number** 699568140439**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2019-05-04 11:53**MOT test number** 274750475496**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) worn down to wear indicator and rear (1.1.13 (a) (i))**MOT #2** 2018-03-30 08:47**MOT test number** 894925710434**Result** ✓ Passed**MOT #1** 2018-03-30 08:47**MOT test number** 642075229474**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2015-05-20
Current registration	
Plate since	2015-05-20

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-31
Last registration	2022-07-22
Complete history	See info



Registration #1	2015-03-31	13 mi
Registration #2	2018-03-30	24.180 mi
Registration #3	2018-03-30	24.180 mi
Registration #4	2019-05-04	29.586 mi
Registration #5	2019-05-10	29.586 mi
Registration #6	2020-10-28	32.749 mi
Registration #7	2022-07-22	32.749 mi
Registration #8	2022-07-22	32.749 mi
Registration #9	2022-07-22	32.749 mi
Registration #10	2022-07-22	32.749 mi
Registration #11	2022-07-22	32.749 mi
Registration #12	2022-07-22	32.749 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1160 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	A382J997