






report date: 2024-03-28

## General information

| Make                | FIAT           |
|---------------------|----------------|
| Model               | 500 LOUNGE     |
| Colour              | Grey           |
| Year of manufacture | 2017           |
| Top speed           | 99 mph         |
| 0 - 60 mph          | 12.9 seconds   |
| Gearbox             | 5 speed Manual |

## Engine & fuel consumption

| Power                   | 69 BHP              |
|-------------------------|---------------------|
| Max. torque             | 102 Nm at 3.000 rpm |
| Engine capacity         | 1.242 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 51.4 mpg            |
| Consumption extra urban | 65.7 mpg            |
| Consumption combined    | 60.1 mpg            |
| CO2 emission            | 110 g/km            |
| CO2 label               | В                   |



CarCheck.co.uk page 1/11




## Internet history

## Entry 1

Date 2021-03-06

Pictures 20

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



## MOT history

| MOT expiry date    | 2024-08-17 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 5          |
| Failed MOT tests   | 0          |
| Total advice items | 6          |
| Total items failed | 0          |

| MOT #5           | 2023-08-18 11:27 |
|------------------|------------------|
| MOT test number  | 397901689448     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-08-17       |

| MOT #4   |  | 2022-05-30 14:07 |
|----------|--|------------------|
| MOT test | number   | 287838621085     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #3     |  | 2021-03-09 16:27 |
|------------|--|------------------|
| MOT test i | number   | 433605618716     |
| Result     |  | ✓ Passed         |
| Advice     | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) | ))               |

| MOT #2   |  | 2020-06-10 08:20 |
|----------|--|------------------|
| MOT test | number   | 375432954484     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

CarCheck.co.uk page 3/11



MOT #1

MOT test number

2020-04-17 10:55

MOT test number

217870759600

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



# Tax & MOT check



| Tax status       | Valid until 1 March |
|------------------|---------------------|
| Days left        | 307                 |
| MOT expiry date  | 17 August 2024      |
| Full MOT history | See MOT history     |

## Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | F          |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |

CarCheck.co.uk page 5/11



## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



## Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



| For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I  |             |
|--|-------------|
|  |             |
| THE STATE OF THE S |             |
|  |             |
| ***************************************  |             |
|  |             |
| THE PARTY OF THE P |             |
| ***************************************  |             |
| *************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FIAT had different number plates.  |             |
|  |             |
| Number of plates   |             |
| Current registration   | NE ZIS      |
| Plate since  |             |
| Current registration   | OK SIE      |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 8/11



## Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2017-04-26 |
| Last registration          | 2023-08-18 |
| Complete history           | See info   |



| Registration #1 | 2017-04-26 | 13 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2020-06-10 | 27.769 mi |
| Registration #3 |            | 11.777 es |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| The FIAT factory car op | otions list is only ava | ailable in the prem | ium report. |
|-------------------------|-------------------------|---------------------|-------------|
|                         |                         |                     |             |

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| 50482 |                 |
| 60501 |                 |
| 60566 |                 |
| 60567 |                 |
| 60569 |                 |

View the complete FIAT factory list for this vehicle <u>here</u>.

More info >

# Safety ratings

| NCAP rating    | ***             |
|----------------|-----------------|
| Adult          | 66%             |
| Children       | 49%             |
| Pedestrian     | 53%             |
| Safety systems | 27%             |
| Overall rating | 52%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1627 mm |
|---------------------|---------|
| Height              | 1488 mm |
| Length              | 3571 mm |
| Wheel base          | 2300 mm |
| Kerb weight         | 865 kg  |
| Max. allowed weight | 1345 kg |

# Additional information

| Fuel delivery                     | Multi-Point Injection |
|-----------------------------------|-----------------------|
| Number of doors                   | 3                     |
| Number of seats                   | 4                     |
| Number of axles<br>Carcheck.co.uk | 2 page 11/11          |