



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D3 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk

**MOT history**

MOT expiry date	2024-05-29
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	18
Total items failed	6

MOT #14	2023-05-30 09:17
MOT test number	953757919920
Result	✓ Passed
Next expiry date	2024-05-29

MOT #13	2023-05-30 09:17
MOT test number	250908366067
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #12	2022-04-21 08:37
MOT test number	434324728562
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #11	2021-04-13 16:06
MOT test number	630512910933
Result	✓ Passed

**MOT #10** 2021-04-13 10:28**MOT test number** 966549197642**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Nail in tyre**MOT #9** 2020-05-18 08:20**MOT test number** 864069084683**Result** ✓ Passed**MOT #8** 2019-05-24 14:30**MOT test number** 251627883510**Result** ✓ Passed**MOT #7** 2019-02-20 11:34**MOT test number** 451610531121**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2018-03-13 12:37**MOT test number** 185568541371**Result** ✓ Passed

**MOT #5** 2018-03-12 13:31**MOT test number** 688121129868**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Outer Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2017-03-18 10:53**MOT test number** 196805826207**Result** ✓ Passed**Advice** Offside Front Tyre side wall rubber cut**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2017-03-17 15:17**MOT test number** 181520430952**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front Tyre side wall rubber cut**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2016-03-17 11:43**MOT test number** 504507128938**Result** ✓ Passed



MOT #1	2015-03-04 16:23
MOT test number	599263865050
Result	✓ Passed
Notice	Front brake pads look low
Notice	Offside rear bumper reflector is deteriorated



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
29 May 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	29 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LR12LJO
Plate since	2019-03-28
Current registration	LR12LJO
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-30
Last registration	2023-05-30
Complete history	See info



Registration #1	2012-03-30	26 mi
Registration #2	2015-03-04	20.410 mi
Registration #3	2016-03-17	24.579 mi
Registration #4	2017-03-17	30.035 mi
Registration #5	2017-03-18	30.035 mi
Registration #6	2018-03-12	34.880 mi
Registration #7	2018-03-13	34.885 mi
Registration #8	2019-02-20	40.481 mi
Registration #9	2019-05-20	45.277 mi
Registration #10	2019-05-20	45.277 mi
Registration #11	2019-05-20	45.277 mi
Registration #12	2019-05-20	45.277 mi
Registration #13	2019-05-20	45.277 mi
Registration #14	2019-05-20	45.277 mi
Registration #15	2019-05-20	45.277 mi
Registration #16	2019-05-20	45.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1773 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number

995146