





report date: 2024-03-28

#### General information

Make	FORD
Model	
Model	FIESTA TITANIUM
Colour	Blue
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Semi-Automatic

### Engine & fuel consumption

Power	104 BHP
Max. torque	150 Nm at 4.200 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	47.9 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/12



### Internet history

#### Entry 1

Date 2021-05-31

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT HISTORY	Μ	OT	history
-------------	---	----	---------

MOT expiry date	2025-01-27
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #9	2024-01-11 14:27
MOT test number	352031707901
Result	✓ Passed
Next expiry date	2025-01-27

MOT #8	2023-01-23 09:35
MOT test number	673797504125
Result	<b>√</b> Passed

MOT #7	2022-01-28 09:45
MOT test number	624146977921
Result	✓ Passed

MOT #6		2021-02-26 13:08
MOT test	number	521574363176
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**MOT #5** 2021-02-26 10:11

**MOT test number** 812402702158

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** TPS light on dash

Fail Offside Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2020-03-11 17:32

MOT test number 666223746770

Result \rightarrow Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** All tyres cracking in treads also front 2-3 mm

**Advice** Nearside Rear Nail in tyre

MOT #3 2020-03-11 16:56

**MOT test number** 567468369051

**Result** X Failed

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** All tyres cracking in treads also front 2-3 mm

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Nearside Rear Nail in tyre

CarCheck.co.uk page 4/12



MOT #2	2019-03-09 12:07
MOT test number	214120050948
Result	<b>✓</b> Passed
MOT #1	2018-02-28 15:45
MOT test number	101115285602
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	27 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	
***************************************	
***************************************	
THE PARTY OF THE P	
***************************************	
*************	
	More info >
	, ,
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-15
Last registration	2024-01-11
Complete history	See info



Registration #1	2015-03-15	26 mi
Registration #2	2018-02-28	9.148 mi
Registration #3	2019-03-09	14.533 mi
Registration #4	2020-03-11	25.133 mi
Registration #5	2020-03-11	25.133 mi
Registration #6	2021-02-26	37.209 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		10.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	86%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1978 mm
Height	1495 mm
Length	3969 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1565 kg

# Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number FM44110