



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT L1 H1 HDI SWB P/V
Colour	Silver
Year of manufacture	-
Top speed	90 mph
0 - 60 mph	17.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-11
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT #18</b>	2022-08-05 11:34
<b>MOT test number</b>	575418231985
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-08-04

<b>MOT #17</b>	2022-08-05 11:34
<b>MOT test number</b>	711962446527
<b>Result</b>	✗ Failed
<b>Pass with rectification</b> Rear fog lamp not working (4.5.1 (a) (ii))	

<b>MOT #16</b>	2021-11-05 09:28
<b>MOT test number</b>	463029994772
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2021-11-02 08:05
<b>MOT test number</b>	434660587153
<b>Result</b>	✗ Failed
<b>Fail</b> Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> Windscreen washer provides insufficient washer liquid (3.5 (a))	
<b>Fail</b> Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	

<b>MOT #14</b>	2020-10-08 08:45
<b>MOT test number</b>	667161137327
<b>Result</b>	✓ Passed
<b>Advice</b> Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
<b>Advice</b> Under body corroded	
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))	
<b>Minor</b> Front Drive shaft joint constant velocity boot severely deteriorated Both (6.1.7 (g) (i))	



MOT #13	2019-09-24 15:11
MOT test number	612821314633
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Non obligatory mirror damaged

MOT #12	2018-10-04 14:36
MOT test number	216427200992
Result	✓ Passed
Advice	Offside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread damage to bottom of number plate (0.1 (b))
Advice	Nearside Oil leak, but not excessive oil leak from driveshaft seal (8.4.1 (a) (i))

MOT #11	2018-10-04 14:36
MOT test number	629035902068
Result	✗ Failed
Advice	Offside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Oil leak, but not excessive oil leak from driveshaft seal (8.4.1 (a) (i))
Pass with rectification	Steering wheel has movement relative to the column such that there is a serious risk of detachment center bolt loose (2.2.1 (a) (ii))
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Offside Rear fog lamp not working (4.5.1 (a) (ii))
Pass with rectification	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt tie loose allowing seepage of grease (6.1.7 (g) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread damage to bottom of number plate (0.1 (b))

**MOT #10** 2017-09-21 14:53**MOT test number** 927385698722**Result** ✓ Passed**MOT #9** 2016-09-22 11:44**MOT test number** 624873516945**Result** ✓ Passed

- Advice** Oil around the gearbox
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside mirror slightly damaged
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-09-22 11:44**MOT test number** 476123106804**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Nearside mirror slightly damaged
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Rear Stop lamp not working (1.2.1b)
- Advice** Oil around the gearbox

**MOT #7** 2015-09-24 10:05**MOT test number** 936566292994**Result** ✓ Passed

- Advice** Nearside mirror slightly damaged

**MOT #6** 2014-09-23 16:46**MOT test number** 495656864218**Result** ✓ Passed**MOT #5** 2013-09-23 09:45**MOT test number** 616016963295**Result** ✓ Passed**MOT #4** 2012-09-25 10:55**MOT test number** 519689862273**Result** ✓ Passed**MOT #3** 2012-09-25 10:55**MOT test number** 279869462267**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2012-02-18 09:11**MOT test number** 639939942066**Result** ✓ Passed**MOT #1** 2011-02-12 09:20**MOT test number** 366893041017**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-02-20
Last registration	2022-08-05
Complete history	<a href="#">See info</a>



Registration #1	2008-02-20	18 mi
Registration #2	2011-02-12	40.518 mi
Registration #3	2012-02-18	54.217 mi
Registration #4	2012-09-25	65.248 mi
Registration #5	2013-09-23	75.548 mi
Registration #6	2014-09-23	87.989 mi
Registration #7	2015-09-24	96.756 mi
Registration #8	2016-09-22	102.549 mi
Registration #9	2016-09-22	102.549 mi
Registration #10	2017-09-21	177.127 mi
Registration #11	2018-09-20	201.377 mi
Registration #12	2019-09-19	225.627 mi
Registration #13	2020-09-18	249.877 mi
Registration #14	2021-09-17	274.127 mi
Registration #15	2022-09-16	298.377 mi
Registration #16	2023-09-15	322.627 mi
Registration #17	2024-09-14	346.877 mi
Registration #18	2025-09-13	371.127 mi
Registration #19	2026-09-12	395.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2194 mm
Height	1980 mm
Length	4805 mm
Kerb weight	1673 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JBAZ0006488