



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Blue
Year of manufacture	2009
Top speed	136 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	370 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-15
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-04-28
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #13 2021-04-29 14:59**MOT test number** 363030571840**Result** ✓ Passed**Next expiry date** 2022-04-28

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front discs inside (1.1.14 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12 2020-03-24 15:58**MOT test number** 510923176299**Result** ✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2019-04-08 11:00**MOT test number** 380651268081**Result** ✓ Passed**Advice** Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10** 2018-05-17 16:16**MOT test number** 265479205202**Result** ✓ Passed**Advice** Nearside Front Lower Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2018-05-16 09:10**MOT test number** 580408798964**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Outer Tyre tread depth below requirements of 1.6mm 225/55/17 (4.1.E.1)**Advice** Nearside Front Lower Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-05-25 15:40**MOT test number** 814886067118**Result** ✓ Passed

**MOT #7** 2016-05-09 09:15**MOT test number** 288344974076**Result** ✓ Passed**MOT #6** 2015-05-12 11:07**MOT test number** 457362835195**Result** ✓ Passed**MOT #5** 2015-05-05 10:47**MOT test number** 828165625126**Result** ✗ Failed

Fail Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #4 2014-05-10 10:07**MOT test number** 308920834162**Result** ✓ Passed**MOT #3** 2013-12-09 16:20**MOT test number** 176143343358**Result** ✓ Passed**MOT #2** 2013-05-08 16:01**MOT test number** 256628723423**Result** ✓ Passed**MOT #1** 2012-05-19 11:39**MOT test number** 166580942175**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
18 July 2021

✕
MOT

Expired:
28 April 2022

Tax status	Expired at 18 July 2021
Days left	1017 days too late
MOT expiry date	28 April 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-05-28
Last registration	2021-04-29
Complete history	See info



Registration #1	2009-05-28	17 mi
Registration #2	2012-05-19	20.419 mi
Registration #3	2013-05-08	25.214 mi
Registration #4	2013-12-09	28.667 mi
Registration #5	2014-05-10	34.911 mi
Registration #6	2015-05-05	52.960 mi
Registration #7	2015-05-12	53.227 mi
Registration #8	2016-05-09	68.240 mi
Registration #9	2016-05-09	68.240 mi
Registration #10	2016-05-09	68.240 mi
Registration #11	2016-05-09	68.240 mi
Registration #12	2016-05-09	68.240 mi
Registration #13	2016-05-09	68.240 mi
Registration #14	2016-05-09	68.240 mi
Registration #15	2016-05-09	68.240 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1729 kg
Max. allowed weight	2216 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	DZ604006935