



General information

Make	MINI
Model	COUNTRYMAN COOPER AUTO COOPER
Colour	White
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H









Internet history

Entry 1

Date	2021-06-19
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-28
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	26
Total items failed	12

MOT #17	2023-11-29 11:12
MOT test number	707066088637
Result	✓ Passed
Next expiry date	2024-11-28
Advice	Towball/hitch not fitted at time of test
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #16** 2023-11-28 16:47**MOT test number** 601365291346**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Towball/hitch not fitted at time of test**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Outer Tyre has ply or cords exposed sidewall (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Items removed from driver's view prior to test**MOT #15** 2022-11-29 15:27**MOT test number** 964558548060**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2022-11-29 14:38**MOT test number** 526338564284**Result** ✗ Failed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2021-11-29 16:21**MOT test number** 190515059623**Result** ✓ Passed

Advice Nearside Front Service brake binding but not excessively Brake pads have worn significantly more than the other side (1.2.1 (f))

MOT #12 2021-11-29 16:21**MOT test number** 283884565599**Result** ✗ Failed

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Service brake binding but not excessively Brake pads have worn significantly more than the other side (1.2.1 (f))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #11 2020-11-19 12:32**MOT test number** 409604813300**Result** ✓ Passed

Advice Offside Rear Seat belt flexible stalk damaged case missing (7.1.2 (b) (i))

Advice Offside Rear Valve stem slightly damaged (5.2.3 (j))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2020-11-19 11:00

MOT test number

580262102064

Result**✗ Failed****Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))**Minor** Offside Windscreen wiper blade defective judders (3.4 (b) (i))**Fail** Front Driver's view of the road through the swept area of the windscreen materially affected by an obstruction air fresheners (3.1 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Seat belt flexible stalk damaged case missing (7.1.2 (b) (i))**MOT #9**

2019-11-05 18:09

MOT test number

216089631549

Result**✓ Passed****Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #8**

2019-11-05 18:09

MOT test number

834224753415

Result**✗ Failed****Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #7** 2018-10-12 15:55**MOT test number** 470133857738**Result** ✓ Passed**Advice** Nearside Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Offside Rear Upper side light N/W**Advice** Offside Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside Rear Upper side light n/w**MOT #6** 2017-09-16 10:59**MOT test number** 790347118260**Result** ✓ Passed**MOT #5** 2017-09-07 12:06**MOT test number** 639389299891**Result** ✗ Failed**Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**MOT #4** 2016-09-10 09:06**MOT test number** 156885090334**Result** ✓ Passed**MOT #3** 2015-09-26 11:35**MOT test number** 165534263081**Result** ✓ Passed**MOT #2** 2014-10-23 09:44**MOT test number** 425846294231**Result** ✓ Passed



MOT #1	2014-09-29 14:44
MOT test number	528812674243
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
28 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-09-29
Last registration	2023-11-29
Complete history	See info



Registration #1	2011-09-29	16 mi
Registration #2	2014-09-29	21.085 mi
Registration #3	2014-10-23	21.100 mi
Registration #4	2015-09-26	26.684 mi
Registration #5	2016-09-10	28.379 mi
Registration #6	2017-09-07	34.732 mi
Registration #7	2017-09-16	34.880 mi
Registration #8	2018-10-12	40.822 mi
Registration #9	2019-11-05	48.564 mi
Registration #10	2019-11-05	48.564 mi
Registration #11	2020-05-29	51.377 mi
Registration #12	2020-05-29	51.377 mi
Registration #13	2020-05-29	51.377 mi
Registration #14	2020-05-29	51.377 mi
Registration #15	2020-05-29	51.377 mi
Registration #16	2020-05-29	51.377 mi
Registration #17	2020-05-29	51.377 mi
Registration #18	2020-05-29	51.377 mi
Registration #19	2020-05-29	51.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1295 kg
Max. allowed weight	1765 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A580J057