



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 R-DESIGN EDITION
Colour	Grey
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.2 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 2

Date	2022-12-09
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-20
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-01
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	11
Total items failed	12

MOT #18	2024-01-31 14:27
MOT test number	165903284963
Result	✓ Passed
Next expiry date	2025-02-01

MOT #17	2024-01-23 14:36
MOT test number	625458050634
Result	✗ Failed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Rear Inner Fuel pipe insecure (6.1.3 (a) (i))
Fail	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #16	2023-01-10 15:31
MOT test number	854182016467
Result	✓ Passed

MOT #15	2023-01-09 13:30
MOT test number	600700613582
Result	✗ Failed
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #14** 2022-02-02 12:31**MOT test number** 749381159506**Result** ✓ Passed**MOT #13** 2021-03-04 12:52**MOT test number** 501894165434**Result** ✓ Passed**Advice** Exhaust condition**MOT #12** 2020-03-10 11:46**MOT test number** 858047392882**Result** ✓ Passed**MOT #11** 2020-03-09 08:33**MOT test number** 403886478671**Result** ✗ Failed**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #10** 2019-06-04 11:15**MOT test number** 767499293459**Result** ✓ Passed

**MOT #9** 2019-06-03 13:39**MOT test number** 716637515553**Result** ✗ Failed**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-05-19 09:04**MOT test number** 994484376811**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil slight (2.7.3)**MOT #7** 2017-06-03 08:57**MOT test number** 681394075672**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside front tyre smooth on inner edge**MOT #6** 2017-06-03 08:57**MOT test number** 593187388961**Result** ✗ Failed**Advice** Offside front tyre smooth on inner edge**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2016-05-14 09:55**MOT test number** 988450788252**Result** ✓ Passed



MOT #4	2016-05-14 09:55
MOT test number	898890010098
Result	✗ Failed
<div>Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)</div>	
MOT #3	2015-06-11 10:50
MOT test number	247892465177
Result	✓ Passed
MOT #2	2015-02-25 11:14
MOT test number	407706155078
Result	✓ Passed
MOT #1	2014-02-28 09:08
MOT test number	758619054076
Result	✓ Passed
<div>Notice Child seat fitted not allowing full inspection of adult belt</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-03-01
Last registration	2024-01-31
Complete history	See info



Registration #1	2011-03-01	11 mi
Registration #2	2014-02-28	22.885 mi
Registration #3	2015-02-25	29.940 mi
Registration #4	2015-06-11	32.094 mi
Registration #5	2016-05-14	37.466 mi
Registration #6	2016-05-14	37.466 mi
Registration #7	2017-06-03	43.758 mi
Registration #8	2017-06-03	43.758 mi
Registration #9	2018-05-19	51.429 mi
Registration #10	2019-06-03	57.518 mi
Registration #11	2019-06-04	57.520 mi
Registration #12	2020-05-20	65.277 mi
Registration #13	2020-05-20	65.277 mi
Registration #14	2020-05-20	65.277 mi
Registration #15	2020-05-20	65.277 mi
Registration #16	2020-05-20	65.277 mi
Registration #17	2020-05-20	65.277 mi
Registration #18	2020-05-20	65.277 mi
Registration #19	2020-05-20	65.277 mi
Registration #20	2020-05-20	65.277 mi
Registration #21	2024-01-31	65.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1379 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1045425