



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ADAM ENERGISED
Colour	Blue
Year of manufacture	2017
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	125 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-06-08
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	4

## MOT #7 2023-05-30 10:22

MOT test number 199173581590

Result ✓ Passed

Next expiry date 2024-06-08

**Advice** Offside Rear lamp condensation**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Inner Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))

## MOT #6 2023-05-26 10:58

MOT test number 299348777264

Result ✗ Failed**Advice** Nearside Front Inner Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear lamp condensation**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))

**MOT #5** 2022-05-30 12:42**MOT test number** 193202230754**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**MOT #4** 2022-05-30 11:58**MOT test number** 562218935085**Result** ✗ Failed**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))**MOT #3** 2021-06-02 11:51**MOT test number** 784122852708**Result** ✓ Passed**MOT #2** 2020-06-09 14:03**MOT test number** 963164656356**Result** ✓ Passed**MOT #1** 2020-05-30 05:16**MOT test number** 684402884163**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
8 June 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	8 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VN17RPU
Plate since	2019-03-29
Current registration	VN17RPU
Plate since	2019-03-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-06-07
Last registration	2023-05-30
Complete history	<a href="#">See info</a>



Registration #1	2017-06-07	14 mi
Registration #2	2020-06-09	13.696 mi
Registration #3	2019-05-29	20.277 mi
Registration #4	2021-06-02	21.856 mi
Registration #5	2019-05-29	20.277 mi
Registration #6	2019-05-29	20.277 mi
Registration #7	2019-05-29	20.277 mi
Registration #8	2019-05-29	20.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1966 mm
Height	1483 mm
Length	3698 mm
Wheel base	2311 mm
Kerb weight	1011 kg
Max. allowed weight	1470 kg

Additional information

Fuel tank capacity	38 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	B12XER -19NN8638LWD