



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | SUZUKI |
| Model | GRAND VITARA VVT |
| Colour | Beige |
| Year of manufacture | 2006 |
| Top speed | 99 mph |
| 0 - 60 mph | 13.4 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 105 BHP |
| Max. torque | 145 Nm at 4.100 rpm |
| Engine capacity | 1.586 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.7 mpg |
| Consumption extra urban | 37.2 mpg |
| Consumption combined | 32.5 mpg |
| CO2 emission | 210 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-10 |
| Pictures | 10 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-21 |
| MOT pass rate | 79 % |
| MOT passed | 15 |
| Failed MOT tests | 4 |
| Total advice items | 30 |
| Total items failed | 5 |

| | |
|------------------|---|
| MOT #19 | 2023-12-18 13:02 |
| MOT test number | 529202681719 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-21 |
| Advice | Tyre slightly damaged/cracking or perishing All four tyres (5.2.3 (d) (ii)) |
| Advice | Entire underside covered with underseal |
| Advice | Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #18 | 2022-12-06 15:28 |
| MOT test number | 944034003148 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #17 | 2021-12-02 12:24 |
| MOT test number | 549546589823 |
| Result | ✓ Passed |
| Advice | Nearside Front Service brake binding but not excessively (1.2.1 (f)) |

**MOT #16** 2020-12-22 15:28**MOT test number** 585070314214**Result** ✓ Passed**Advice** Underside corrosion**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**Advice** Brake disc worn, pitted or scored, but not seriously weakened offside and nearside front (1.1.14 (a) (ii))**MOT #15** 2019-11-27 10:20**MOT test number** 533297349755**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Advice** Nearside Front Coil spring corroded at the top (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded at the top (5.3.1 (b) (i))**MOT #14** 2018-11-29 11:02**MOT test number** 601400282212**Result** ✓ Passed**MOT #13** 2018-11-29 11:02**MOT test number** 855673233002**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #12** 2017-11-22 10:34**MOT test number** 578911615681**Result** ✓ Passed

**MOT #11** 2017-11-22 10:34**MOT test number** 648752741596**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #10** 2016-11-30 11:16**MOT test number** 523727551768**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened at rear of disc (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened at rear of disc (3.5.1i)**MOT #9** 2015-12-01 10:36**MOT test number** 893664771940**Result** ✓ Passed**MOT #8** 2014-12-02 10:27**MOT test number** 728946334354**Result** ✓ Passed**MOT #7** 2013-06-24 11:13**MOT test number** 297465273405**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-06-25 10:00**MOT test number** 957367472170**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-06-20 11:29**MOT test number** 919322672106**Result** ✗ Failed**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-06-20 09:25**MOT test number** 227601471495**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f o/s/f brake discs slightly corroded on inner face**MOT #3** 2010-10-12 11:48**MOT test number** 191795680251**Result** ✓ Passed**Notice** Nail in nearside front tyre**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** N/s/f o/s/f brake discs slightly corroded on inner face



MOT #2 2010-10-12 11:48

MOT test number 870895380259

Result ✗ Failed

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Nail in nearside front tyre

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice N/s/f o/s/f brake discs slightly corroded on inner face

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2009-09-29 16:27

MOT test number 754982079214

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 21 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2006-10-12 |
| Last registration | 2023-12-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-10-12 | 28 mi |
| Registration #2 | 2009-09-29 | 17.719 mi |
| Registration #3 | 2010-10-12 | 21.208 mi |
| Registration #4 | 2011-06-20 | 23.002 mi |
| Registration #5 | 2012-06-20 | 26.126 mi |
| Registration #6 | 2012-06-25 | 26.126 mi |
| Registration #7 | 2013-06-24 | 28.645 mi |
| Registration #8 | 2014-12-02 | 30.437 mi |
| Registration #9 | 2015-12-01 | 31.857 mi |
| Registration #10 | 2016-11-30 | 33.171 mi |
| Registration #11 | 2019-05-29 | 33.171 mi |
| Registration #12 | 2019-05-29 | 33.171 mi |
| Registration #13 | 2019-05-29 | 33.171 mi |
| Registration #14 | 2019-05-29 | 33.171 mi |
| Registration #15 | 2019-05-29 | 33.171 mi |
| Registration #16 | 2019-05-29 | 33.171 mi |
| Registration #17 | 2019-05-29 | 33.171 mi |
| Registration #18 | 2019-05-29 | 33.171 mi |
| Registration #19 | 2019-05-29 | 33.171 mi |
| Registration #20 | 2019-05-29 | 33.171 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1695 mm |
| Length | 4005 mm |
| Wheel base | 2440 mm |
| Kerb weight | 1445 kg |
| Max. allowed weight | 1800 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | M16A-1159866 |