





report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D3 BUSINESS EDITION
Colour	Black
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-13

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-30
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #8		2023-12-01 17:34
MOT test	number	432681658526
Result		✓ Passed
Next expi	ry date	2024-11-30
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2022-11-09 13:10
MOT test number	816262915169
Result	✓ Passed
Advice Both rear tyres worn inner edges	

MOT #6		2022-11-09 13:10
MOT test number		500846357323
Result		× Failed
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	
Advice Both rear tyres	worn inner edges	
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

699043628346

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Headlamp cleaning device inoperative (4.1.6 (a) (i))

MOT test number
912493650366

Result
Minor Offside Front Headlamp cleaning device inoperative (4.1.6 (a) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT test number

Result

725703004466

Result

2019-04-18 14:58

MOT test number

251935115064

Result

Advice Rear Brake lining(s) wearing thin brake discs lipped. pads advise (1.1.13 (a) (ii))

MOT test number

Fail Offside Front Tyre has ply or cords exposed tracking needed (5.2.3 (d) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Rear Brake lining(s) wearing thin brake discs lipped. pads advise (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



FY16UOD report date: 2024-03-28

Tax & MOT check





Expires: 30 November 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



funder scincole

FY16UOD

report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLVO had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-17
Last registration	2023-12-01
Complete history	See info



Registration #1	2016-05-17	11 mi
Registration #2	2019-04-18	90.816 mi
Registration #3	2019-04-18	90.816 mi
Registration #4	2020-10-22	126.897 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1618 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles 2

Engine number 1529493