





report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 145
Colour	Grey
Year of manufacture	2008
Top speed	119 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	1



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-23

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-21
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	30
Total items failed	5

MOT #20	2023-09-21 15:42
MOT test number	126116151316
Result	✓ Passed
Next expiry date	2024-09-21
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #19	2023-09-19 08:24
MOT test i	number 532723031312
Result	★ Failed
MAJOR	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #18		2022-09-14 09:12
MOT test num	ber	166352748950
Result		✓ Passed
Advice Rea	ar Brake disc worn, pitted or scored, but not seriously weak	kened NSR&OSR (1.1.14 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #17 2022-09-13 08:49

MOT test number 901743706638

Result X Failed

MAJOR Offside Rear Anti-roll bar linkage ball joint excessively worn Drop link (5.3.4 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened All four(NSF&OSF + NSR&OSR)brake disc worn and lipped (1.1.14 (a) (ii))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn Lower arm rear bush (5.3.4 (a) (i))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn Lower arm rear bush (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge NSF&OSF tyre worn to bald on the inner edge (5.2.3 (e))

MAJOR Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Inner edge. Marked. 205/55 R16 94W (5.2.3 (d) (i))

MOT #16 2021-09-22 11:37

MOT test number 548569109094

Result
✓ Passed

MOT #15 2021-09-22 11:37

MOT test number 254703999846

Result X Failed

Pass with rectification Offside Front Direction indicator incorrect colour (4.4.3 (a))

Pass with rectification Nearside Front Direction indicator incorrect colour (4.4.3 (a))

MOT #14 2020-11-04 11:52

MOT test number 109455832364

Result ✓ Passed

Advice Exhaust system corroded

Advice General underside corrosion

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #13 2020-11-04 09:58

MOT test number 800839292036

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

Advice General underside corrosion

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Exhaust system corroded

MOT #12 2019-11-05 12:40

MOT test number 852714194470

Result
✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2018-10-30 15:28

MOT test number 660706961849

Result
✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2017-10-26 10:25

MOT test number 671301568959

Result ✓ Passed

Advice Offside Rear tyre perishing

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9 2017-10-26 10:25

MOT test number 798075729095

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Offside Rear tyre perishing

MOT #8 2016-11-11 09:04

MOT test number 348667493369

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2016-11-11 09:04

MOT test number 943891763909

Result X Failed

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-11-10 11:20

MOT test number 375858999928

Result \(\sqrt{Passed} \)

MOT #5 2015-11-09 12:54

MOT test number 978554683229

Result X Failed

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #4 2014-11-07 10:58

MOT test number 736291014317

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2		2012-11-14 11:24
MOT test	number	347879412326
Result		✓ Passed
Notice	Advise front tyres worn/wearing on the inner edges	

MOT #1	2011-12-06 12:03
MOT test number	538990641395
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manus .	

manus .	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Fiate since	mn.n.n
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14





report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-12-31
Last registration	2023-09-21
Complete history	See info



Registration #1	2008-12-31	29 mi
Registration #2	2011-12-06	11.490 mi
Registration #3	2012-11-14	15.232 mi
Registration #4	2013-11-11	18.049 mi
Registration #5	2014-11-07	20.509 mi
Registration #6	2015-11-09	22.402 mi
Registration #7	2015-11-10	22.402 mi
Registration #8	2016-11-11	25.219 mi
Registration #9	2016-11-11	25.219 mi
Registration #10	2017-10-26	27.621 mi
Registration #11	2017-10-26	27.621 mi
Registration #12		77,777 46
Registration #13		71.777 66
Registration #14		77,777 46
Registration #15		71.777 66
Registration #16		71.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 66

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1435 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	53
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14

Number of axles 2
Engine number 8T29731