



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS
Colour	Blue
Year of manufacture	2012
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-07-12
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-09
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	18
Total items failed	21

MOT #17	2023-10-10 16:13
MOT test number	948138204643
Result	✓ Passed
Next expiry date	2024-10-09
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2023-10-02 11:43
MOT test number	814689360069
Result	✗ Failed
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Headlamp insecure (4.1.1 (c))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Headlamp insecure (4.1.1 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #15	2022-10-06 12:44
MOT test number	386262714212
Result	✓ Passed
Advice	Under the vehicle general paint with black spray rust

MOT #14	2022-03-07 17:50
MOT test number	937857263938
Result	✓ Passed

MOT #13	2022-03-07 11:03
MOT test number	540432720801
Result	✗ Failed
Fail	Brake pad(s) less than 1.5 mm thick N/S/F & O/S/F & N/S/R & O/S/R (1.1.13 (a) (ii))
Fail	Emissions not tested Has a major leak of exhaust gases (8.2.1.2 (d))
Fail	Tyre tread depth below requirements of 1.6mm N/S/F & O/S/F (5.2.3 (e))
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12	2021-02-17 14:30
MOT test number	861046361230
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-02-17 09:15
MOT test number	829078643166
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Emissions not tested due to exhaust blow (8.2.1.2 (d))

**MOT #10** 2020-02-20 09:06**MOT test number** 376784135385**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases centre pipe. (6.1.2 (a))**MOT #9** 2019-02-15 13:51**MOT test number** 594738957768**Result** ✓ Passed**MOT #8** 2019-02-15 09:29**MOT test number** 519368663247**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn rearmost (5.3.4 (a) (i))**Advice** Exhaust heat shield insecure**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn rearmost (5.3.4 (a) (i))**MOT #7** 2018-02-22 13:57**MOT test number** 765152029720**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rearmost (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rearmost (2.4.G.2)

**MOT #6**

2018-02-22 09:08

MOT test number

660584508039

Result**✗ Failed****Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rearmost (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rearmost (2.4.G.2)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #5**

2017-02-20 11:33

MOT test number

932179162921

Result**✓ Passed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4**

2016-02-22 14:13

MOT test number

782765536645

Result**✓ Passed****MOT #3**

2016-02-22 09:21

MOT test number

207302514026

Result**✗ Failed****Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2015-02-23 15:48
MOT test number	826514755025
Result	✓ Passed

MOT #1	2015-02-23 09:12
MOT test number	115134855412
Result	✗ Failed
<div><div>Fail</div>Offside Headlamp aim too low and too far to the right. (1.8)</div> <div><div>Advice</div>Offside Rear Shock absorber has a light misting of oil (2.7.3)</div> <div><div>Fail</div>Nearside Headlamp aim too low and too far to the right. (1.8)</div> <div><div>Fail</div>Nearside Rear Shock absorber has a serious fluid leak (2.7.3)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 October 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	 SH61VZV
Plate since	2019-09-28
Current registration	 SH61VZV
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-02-19
Last registration	2023-10-10
Complete history	See info



Registration #1	2012-02-19	7 mi
Registration #2	2015-02-23	25.845 mi
Registration #3	2015-02-23	25.845 mi
Registration #4	2016-02-22	30.564 mi
Registration #5	2016-02-22	30.564 mi
Registration #6	2017-02-20	35.782 mi
Registration #7	2018-02-22	41.537 mi
Registration #8	2018-02-22	41.537 mi
Registration #9	2019-02-15	46.384 mi
Registration #10	2019-02-15	46.384 mi
Registration #11	2020-02-15	51.231 mi
Registration #12	2020-02-15	51.231 mi
Registration #13	2021-02-15	56.078 mi
Registration #14	2021-02-15	56.078 mi
Registration #15	2022-02-15	60.925 mi
Registration #16	2022-02-15	60.925 mi
Registration #17	2023-02-15	65.772 mi
Registration #18	2023-02-15	65.772 mi
Registration #19	2023-10-10	70.619 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1470 kg
Max. allowed weight	2085 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 10228475