



report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ TDVI SPORT PREMIUM
Colour	Blue
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-08
Pictures	38
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-08
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	37
Total items failed	14

MOT #18	2023-04-05 12:43
MOT test number	106037482845
Result	✓ Passed
Next expiry date	2024-04-08

MOT #17	2022-03-23 11:11
MOT test number	772473167796
Result	✓ Passed

MOT #16	2022-03-22 14:26
MOT test number	838065880602
Result	✗ Failed

- Advice** Oil leak, but not excessive rear diff (8.4.1 (a) (i))
- Advice** Front wipers smearing
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Offside Rear Upper Suspension arm pin or bush excessively worn track arm (5.3.4 (a) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #15** 2021-04-09 09:07**MOT test number** 178453986672**Result** ✓ Passed**MOT #14** 2020-10-28 11:40**MOT test number** 677572295231**Result** ✓ Passed**MOT #13** 2020-10-27 16:50**MOT test number** 934910739715**Result** ✗ Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Front Position lamp not working Both (4.2.1 (a) (ii))

MOT #12 2019-09-25 10:48**MOT test number** 247731893277**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11 2018-05-25 10:49**MOT test number** 508262811496**Result** ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm recorded (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm recorded (5.2.3 (e))



MOT #10	2017-05-12 15:00
MOT test number	759540228659
Result	✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #9	2017-05-08 11:33
MOT test number	987155792197
Result	✗ Failed
Fail	Nearside Front Brake hose ferrule excessively corroded (3.6.B.4e)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Fail	Nearside Rear Brake hose ferrule excessively corroded (3.6.B.4e)
Fail	Offside Rear Brake hose ferrule excessively corroded (3.6.B.4e)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Front lower suspension arm bushes are becoming worn/soft
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Fail	Offside Front Brake hose ferrule excessively corroded (3.6.B.4e)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Rear Brake hose ferrule excessively corroded (3.6.B.4e)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2016-05-20 12:14**MOT test number** 102471082384**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #7 2015-04-10 10:02**MOT test number** 729200405140**Result** ✓ Passed

- Notice** All brake flexi ferrule ends are slightly corroded

MOT #6 2014-04-16 15:36**MOT test number** 885746104100**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front brake pads/discs becoming worn

MOT #5 2013-04-19 13:56**MOT test number** 106229803195**Result** ✓ Passed

**MOT #4** 2013-04-19 13:56**MOT test number** 438079003163**Result** ✗ Failed

- Pass with rectification** Bonnet cannot be secured in the closed position (8.4.1)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2012-04-18 15:37**MOT test number** 778649502176**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2011-04-26 15:13**MOT test number** 716386011155**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1 2011-04-26 12:50

MOT test number 568026611193

Result ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear fog lamp emits a light other than red (1.3.2e)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Direction indicator deteriorated, but still visible from a reasonable distance (1.4.A.2e)



Tax & MOT check

X

Untaxed

Tax expired:
15 March 2024

X

MOT

Expired:
8 April 2024

Tax status	Expired at 15 March 2024
Days left	46 days too late
MOT expiry date	8 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-29
Current registration	 XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-30
Last registration	2023-04-05
Complete history	See info



Registration #1	2008-04-30	17 mi
Registration #2	2011-04-26	12.080 mi
Registration #3	2011-04-26	12.080 mi
Registration #4	2012-04-18	16.008 mi
Registration #5	2013-04-19	21.683 mi
Registration #6	2014-04-16	26.121 mi
Registration #7	2015-04-10	30.485 mi
Registration #8	2016-05-20	38.176 mi
Registration #9	2017-05-08	42.467 mi
Registration #10	2017-05-12	42.467 mi
Registration #11	2018-05-20	51.377 mi
Registration #12	2019-05-20	51.377 mi
Registration #13	2020-05-20	51.377 mi
Registration #14	2021-05-20	51.377 mi
Registration #15	2022-05-20	51.377 mi
Registration #16	2023-05-20	51.377 mi
Registration #17	2024-05-20	51.377 mi
Registration #18	2025-05-20	51.377 mi
Registration #19	2026-05-20	51.377 mi

More info >



Dimensions & weight

Width	1898 mm
Height	1455 mm
Length	5090 mm
Wheel base	3034 mm
Kerb weight	1659 kg
Max. allowed weight	2283 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	03035337G