



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 T3 R-DESIGN
Colour	Red
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.592 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-09-22
Pictures	28
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-20
Pictures	28
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #13	2023-08-17 16:04
MOT test number	464818122035
Result	✓ Passed
Next expiry date	2024-08-29

MOT #12	2023-08-15 13:50
MOT test number	793605590743
Result	✗ Failed
Fail	Offside Rear Lower Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Nearside Rear Inner Nail in tyre

MOT #11	2022-08-30 17:05
MOT test number	115675750755
Result	✓ Passed
Advice	Rear Rear seat belts not tested, seat belts inaccessible.
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Lower Coil spring corroded Both sides (5.3.1 (b) (i))

**MOT #10** 2021-03-11 16:18**MOT test number** 578887827062**Result** ✓ Passed**MOT #9** 2020-03-20 17:47**MOT test number** 608984392034**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-02-15 17:37**MOT test number** 457402184517**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-02-12 11:51**MOT test number** 306969243589**Result** ✓ Passed**Advice** Offside front tyre wearing on inner edge**Advice** Nearside front tyre worn on inner edge advise replacement**MOT #6** 2017-02-21 08:08**MOT test number** 263549139330**Result** ✓ Passed**Advice** Nearside front tyre wearing on inner edge**MOT #5** 2016-05-27 15:33**MOT test number** 293418761005**Result** ✓ Passed

**MOT #4** 2016-05-25 11:18**MOT test number** 988692321655**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nail in nsr tyre outside edge. osf tyre worn on inside**MOT #3** 2015-05-22 11:24**MOT test number** 166612545178**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-03-05 11:05**MOT test number** 318034164004**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-03-05 11:05**MOT test number** 539044964046**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-03
Last registration	2023-08-17
Complete history	See info



Registration #1	2011-06-03	18 mi
Registration #2	2014-03-05	23.449 mi
Registration #3	2015-05-22	34.027 mi
Registration #4	2016-05-25	41.546 mi
Registration #5	2016-05-27	41.457 mi
Registration #6	2017-02-21	47.879 mi
Registration #7	2018-02-12	55.752 mi
Registration #8	2019-02-15	63.866 mi
Registration #9	2020-05-20	75.377 mi
Registration #10	2021-05-20	85.377 mi
Registration #11	2022-05-20	95.377 mi
Registration #12	2023-05-20	105.377 mi
Registration #13	2024-05-20	115.377 mi
Registration #14	2025-05-20	125.377 mi
Registration #15	2026-05-20	135.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1484 mm
Length	4028 mm
Wheel base	2775 mm
Kerb weight	1519 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1015993
---------------	---------