



**A063DHD**

report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | SUZUKI            |
| Model               | SWIFT SZ4         |
| Colour              | Black             |
| Year of manufacture | 2013              |
| Top speed           | 99 mph            |
| 0 - 60 mph          | 13.5 seconds      |
| Gearbox             | 4 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 94 BHP              |
| Max. torque             | 118 Nm at 4.800 rpm |
| Engine capacity         | 1.242 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 41.5 mpg            |
| Consumption extra urban | 57.7 mpg            |
| Consumption combined    | 50.4 mpg            |
| CO2 emission            | 128 g/km            |
| CO2 label               | D                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-04                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-04 |
| MOT pass rate      | 67 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 4          |
| Total advice items | 24         |
| Total items failed | 6          |

|                  |   |
|------------------|---|
| MOT #12          | 2023-10-05 12:29  |
| MOT test number  | 256913771588  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-10-04  |
| Advice           | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice           | Oil leak, but not excessive (8.4.1 (a) (i))   |
| Advice           | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                 |
| Advice           | Rear wiper blade rubber split   |
| Advice           | Offside Rear Nail in tyre   |
| Advice           | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |

**MOT #11** 2023-10-04 14:42**MOT test number** 554219697709**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear wiper blade rubber split**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Nail in tyre**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2022-08-11 15:28**MOT test number** 141268503196**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #9** 2022-08-11 14:35**MOT test number** 867798720156**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #8** 2021-06-18 07:42**MOT test number** 207196263631**Result** ✓ Passed**MOT #7** 2021-06-18 07:42**MOT test number** 356074767461**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #6** 2020-12-09 09:09**MOT test number** 215387552628**Result** ✓ Passed**MOT #5** 2019-12-13 09:26**MOT test number** 990399020560**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge BOTH. (5.2.3 (e))**MOT #4** 2019-12-10 11:38**MOT test number** 961601899933**Result** ✗ Failed**Advice** Rear Tyre worn close to legal limit/worn on edge BOTH. (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Tyre has ply or cords exposed OUTER SIDE WALL. (5.2.3 (d) (ii))

**MOT #3** 2018-09-26 14:08**MOT test number** 459565301543**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2017-10-17 11:08**MOT test number** 469106834959**Result** ✓ Passed**Advice** Wipers poor**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #1** 2016-08-19 14:02**MOT test number** 376711408357**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 February 2024

✓

MOT

Expires:  
4 October 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 1 February 2024      |
| Days left        | 87 days too late                |
| MOT expiry date  | 4 October 2024                  |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-29 |
| Current registration | *****      |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2013-10-22               |
| Last registration          | 2023-10-05               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-10-22 | 24 mi     |
| Registration #2  | 2016-08-19 | 16.986 mi |
| Registration #3  | 2017-10-17 | 26.105 mi |
| Registration #4  | 2018-09-26 | 34.389 mi |
| Registration #5  | 2019-12-10 | 40.308 mi |
| Registration #6  | 2019-12-13 | 40.314 mi |
| Registration #7  | 2020-12-09 | 40.367 mi |
| Registration #8  | 2020-12-09 | 40.367 mi |
| Registration #9  | 2020-12-09 | 40.367 mi |
| Registration #10 | 2020-12-09 | 40.367 mi |
| Registration #11 | 2020-12-09 | 40.367 mi |
| Registration #12 | 2020-12-09 | 40.367 mi |
| Registration #13 | 2020-12-09 | 40.367 mi |
| Registration #14 | 2020-12-09 | 40.367 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 94%                             |
| Children       | 82%                             |
| Pedestrian     | 62%                             |
| Safety systems | 71%                             |
| Overall rating | 83%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1695 mm |
| Height              | 1510 mm |
| Length              | 3850 mm |
| Wheel base          | 2430 mm |
| Kerb weight         | 1085 kg |
| Max. allowed weight | 1485 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 42 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Number of axles    | 2                     |
| Engine number      | K12B-1724220          |