





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|-----------------|
| Model | FUSION FUSION 1 |
| Colour | Green |
| Year of manufacture | 2004 |
| Top speed | 99 mph |
| 0 - 60 mph | 15.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 67 BHP |
|-------------------------|---------------------|
| Max. torque | 160 Nm at 2.000 rpm |
| Engine capacity | 1.399 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 117 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 5


Date 2021-10-05


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 4

| Date | 2021-07-31 |
|------|------------|
|------|------------|


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3


Date 2021-07-24


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

| Date | 2021-07-11 |
|------|------------|
| | |


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk



report date: 2024-03-28

| | _ | | | | |
|-------|-----|---|----|---------------|-----|
| 11/1/ | TC | n | | $\overline{}$ | r\/ |
| IVIL | , , | | 51 | LU. | ıv |
| | | | | | . , |

| MOT expiry date | 2025-04-12 |
|--------------------|------------|
| MOT pass rate | 65 % |
| MOT passed | 17 |
| Failed MOT tests | 9 |
| Total advice items | 26 |
| Total items failed | 26 |

| MOT #26 | 2024-03-23 15:05 |
|------------------|------------------|
| MOT test number | 479884261999 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-12 |

| MOT #25 | | 2023-04-13 16:08 |
|----------|---|------------------|
| MOT test | number | 510141074971 |
| Result | | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) | |

CarCheck.co.uk page 3/16



MOT #24

ML04FVK

report date: 2024-03-28

2023-03-16 14:11

MOT test number 237890646450

Result X Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Headlamp lens slightly defective both front (4.1.1 (b) (i))

Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

Fail Nearside Headlamp aim too low (4.1.2 (a))

MOT #23 2022-03-12 09:32

MOT test number 982005900276

Minor Nearside Headlamp lens slightly defective lens scratched (4.1.1 (b) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #22 2021-03-06 10:49

MOT test number 676772379226

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-28

Passed

MOT #21 2021-03-06 10:49

MOT test number 343663976508

Result **X** Failed

Pass with rectification Offside Front Brake hose excessively stretched (1.1.12 (b) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #20 2020-03-17 08:57

MOT test number 792901923312

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2020-03-10 10:12

MOT test number 815991548758

Result × Failed

Fail Nearside Brake pipe excessively corroded Front to Rear (1.1.11 (c))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Offside Brake pipe excessively corroded Front to Rear (1.1.11 (c)) Fail

Offside Rear fog lamp not working (4.5.1 (a) (ii)) Fail

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Offside Front Brake pipe excessively corroded (1.1.11 (c)) Fail

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number

Result

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing 195 60 R15 (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing 195 60 R15 (5.2.3 (d) (ii))

MOT #17 2019-03-29 13:36 **MOT** test number 957219651715 Result × Failed Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing 195 60 R15 (5.2.3 (d) (ii)) Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing 195 60 R15 (5.2.3 (d) (ii))

MOT #16 2018-05-10 14:05

MOT test number 641234655299

Result ✓ Passed

MOT #15

MOT test number

283773603838

Result

X Failed

Offside Front Shock absorber has a serious fluid leak (2.7.3)

 MOT #14
 2017-01-26 11:26

 MOT test number
 798000647656

 Result
 ✓ Passed

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT test number

657271108711

Result

Fail Exhaust has a major leak of exhaust gases (7.1.2)

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #12

MOT test number

110681045927

Result

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Nail in nearside rear tyre

MOT test number

856647646345

Result

Advice Nail in nearside rear tyre

Fail Nearside Front coil spring fractured (2.4.C.1a)

Fail Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

 MOT #10
 2014-03-01 11:45

 MOT test number
 225910464014

 Result
 ✓ Passed

CarCheck.co.uk page 7/16



report date: 2024-03-28

| MOT #9 | 2013-03-06 13:17 |
|---|------------------|
| MOT test number | 699555863042 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #8 | 2012-02-24 15:20 |
|-------------------------|--|
| MOT test number | 358595952001 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2012-02-24 15:20 |
| MOT test number | 138795852493 |
| Result | ★ Failed |
| Pass with rectification | Nearside Front Windscreen wiper does not clear the windscreen effectively |
| (8.2.2) | |
| Pass with rectification | Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3) |
| Pass with rectification | Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |

| MOT #6 | 2011-03-08 15:27 |
|--|------------------|
| MOT test number | 129347961059 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2011-03-08 13:47 |
| MOT test number | 456947361069 |
| Result | X Failed |
| Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b) | |

| MOT #4 | 2010-03-03 16:09 |
|-----------------|------------------|
| MOT test number | 904092760058 |
| Result | ✓ Passed |

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #3 2009-03-04 11:10

MOT test number 141613569411

Result ✓ Passed

Advice Nearside Front brake disc slightly pitted (3.5.1h)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2008-02-06 14:47

MOT test number 993727838024

Result ✓ Passed

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #1 2007-03-26 14:59

MOT test number 280055487081

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 3 |
| MOT expiry date | 12 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



MLO4FVK report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | |
|--|-------------|
| | |
| HARMAN CONTRACTOR CONT | |
| | |
| *************************************** | |
| ******* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | NE AIR |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 13/16



ML04FVK report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >


CarCheck.co.uk page 14/16



MLO4FVK report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 31 |
| First mileage registration | 2004-03-31 |
| Last registration | 2024-03-23 |
| Complete history | See info |



| Registration #1 | 2004-03-31 | 19 mi |
|------------------|------------|------------|
| Registration #2 | 2007-03-26 | 36.629 mi |
| Registration #3 | 2008-02-06 | 47.886 mi |
| Registration #4 | 2009-03-04 | 58.758 mi |
| Registration #5 | 2010-03-03 | 65.140 mi |
| Registration #6 | 2011-03-08 | 70.403 mi |
| Registration #7 | 2011-03-08 | 70.405 mi |
| Registration #8 | 2012-02-24 | 74.308 mi |
| Registration #9 | 2013-03-06 | 78.901 mi |
| Registration #10 | 2014-03-01 | 84.920 mi |
| Registration #11 | 2016-02-09 | 86.340 mi |
| Registration #12 | 2016-02-10 | 86.340 mi |
| Registration #13 | 2017-01-25 | 89.526 mi |
| Registration #14 | 2017-01-26 | 89.532 mi |
| Registration #15 | 2018-05-08 | 99.595 mi |
| Registration #16 | 2018-05-10 | 99.602 mi |
| Registration #17 | | 11.177 mi |
| Registration #18 | | 11.117 es |
| Registration #19 | | 11.777 mi |
| Registration #20 | | 11.117 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 11.177 es |
| Registration #23 | | 11.177 es |
| Registration #24 | | 11.177 es |
| Registration #25 | | 11.177 es |
| Registration #26 | | 0.00 44 |
| CarCheck.co.uk | | page 15/16 |

| Registration #27 | 11,777 66 |
|------------------|-----------|
| Registration #28 | 71.777 es |
| Registration #29 | 0.777 es |
| Registration #30 | 11.777 es |
| Registration #31 | 9.70 es |

More info >



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1952 mm |
|---------------------|---------|
| Height | 1534 mm |
| Length | 4020 mm |
| Wheel base | 2485 mm |
| Kerb weight | 1102 kg |
| Max. allowed weight | 1640 kg |

Additional information

| Fuel tank capacity | 45 l |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 16/16 |