





report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 E ACENTA
Colour	Red
Year of manufacture	2015
Top speed	76 mph
0 - 60 mph	14.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm
Fuel type	Electricity



CarCheck.co.uk page 1/11




Internet history


Entry 1


 Date
 2021-06-24


 Pictures
 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT	history	,

MOT expiry date	2024-09-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #8	2023-08-28 06:13
MOT test number	284354445603
Result	✓ Passed
Next expiry date	2024-09-19

MOT #7		2022-09-20 14:44
MOT test	number	516000111656
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside rear light lens damaged	

MOT #6	2022-09-16 10:49
MOT test number	463431892747
Result	× Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside rear light lens damaged	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number 541255245214

Result ✓ Passed

MOT #4 2021-04-30 13:09

MOT test number 672121570973

Result

Passed

MOT #3 2019-06-11 08:48

MOT test number 736949672230

Result \(\sqrt{Passed} \)

Advice Rear high level brake light not working

MOT #2 2018-06-15 15:49

MOT test number 562065007384

MOT #1 2018-06-15 12:49

MOT test number 419145719135

Result ★ Failed

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Nail in tyre X2

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords

(5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29





Days left 155

MOT expiry date 19 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		.N

	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK MIN	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-15
Last registration	2023-08-28
Complete history	See info



Registration #1	2015-06-15	22 mi
Registration #2	2018-06-15	7.258 mi
Registration #3	2018-06-15	7.258 mi
Registration #4	2019-06-11	9.535 mi
Registration #5	2021-04-30	11.147 mi
Registration #6		11.777 es
		11.777 ea 11.777 ea
Registration #6		11.777 es 11.777 es
Registration #6 Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	2
Engine number	082233A

CarCheck.co.uk page 11/11