





General information

| Make | VOLVO | |
|---------------------|-------------------------------------|--|
| Model | XC90 D5 POWERPULSE R-DESIGN PRO AWD | |
| Colour | White | |
| Year of manufacture | 2016 | |
| Top speed | 137 mph | |
| 0 - 60 mph | 7.4 seconds | |
| Gearbox | 8 speed automatic | |

Engine & fuel consumption

| Power | 231 BHP |
|-------------------------|---------------------|
| Max. torque | 480 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 45.6 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |





Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-08-02 |
| Pictures | 50 |
| Listing price | View report |



source: cargurus.co.uk

| EULLY T | |
|---------|--|
|---------|--|

Date

Pictures

Listing price

2021-08-01

65

View report



source: autotrader.co.uk









MOT history

| MOT expiry date | 2024-08-09 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 1 |

| MOT #6 | 2023-08-07 11:51 |
|------------------|------------------|
| MOT test number | 508688673272 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-09 |

| MOT #5 | 2022-08-03 12:26 |
|----------|---|
| MOT test | number 792924680014 |
| Result | ✓ Passed |
| Minor | Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |
| Minor | Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |

| MOT #4 | 2021-08-10 15:55 |
|-----------------|------------------|
| MOT test number | 500563542169 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2020-09-11 11:13 |

| MOT test number | 288167683535 |
|-----------------------------------|--------------|
| Result | ✓ Passed |
| Advice Offside Front Nail in tyre | |



| GU66SYP |
|-------------------------|
| report date: 2024-03-28 |

✓ Passed

| MOT #2 | 2020-09-11 10:32 |
|---|---------------------------|
| MOT test number | 268270872888 |
| Result | 🗙 Failed |
| AdviceOffside Front Nail in tyreFailNearside Rear Tyre has a cut in excess of the requirements deep enough (5.2.3 (d) (i)) | to reach the ply or cords |
| MOT #1 | 2019-09-23 15:29 |
| MOT test number | 294048319659 |

Result



Tax & MOT check

| Tax 1 August 2024 | / xed | Expires: 9 August 2024 | ✓ МОТ |
|----------------------|----------|----------------------------------|------------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 94 |
| MOT expiry date | | | 9 August 2024 |
| Full MOT history | | | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLI |
| | |
| Date | 1. the second se |
| Category | ante |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ana | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Correct registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow



GU66SYP report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 9 |
| First mileage registration | 2016-09-30 |
| Last registration | 2023-08-07 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-09-30 | 23 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-09-23 | 32.392 mi |
| Registration #3 | 2020-09-11 | 39.832 mi |
| Registration #4 | 2020-09-11 | 39.834 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| 50566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 97% |
| Children | 87% |
| Pedestrian | 72% |
| Safety systems | 94% |
| Overall rating | 89% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2008 mm |
| Height | 1776 mm |
| Length | 4950 mm |
| Wheel base | 2984 mm |
| Kerb weight | 2009 kg |
| Max. allowed weight | 2750 kg |
| Additional information | |
| Fuel tank capacity | 71 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 1801395 |