



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Silver
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-07-12
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	28
Total items failed	4

MOT #17 2023-07-13 16:31

MOT test number 298275007039

Result ✓ Passed

Next expiry date 2024-07-12

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #16 2023-07-13 15:03

MOT test number 206955504763

Result ✗ Failed

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #15**

2022-05-12 14:10

**MOT test number**

632692061036

**Result**

✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #14**

2021-01-11 15:44

**MOT test number**

600715488870

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #13**

2019-05-02 14:49

**MOT test number**

749814362464

**Result**

✓ Passed

**MOT #12** 2018-10-22 13:58**MOT test number** 888354471060**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2018-10-22 13:58**MOT test number** 790308701902**Result** ✗ Failed

- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2018-04-23 13:15**MOT test number** 499778695644**Result** ✓ Passed**MOT #9** 2017-10-24 15:43**MOT test number** 114079382351**Result** ✓ Passed**MOT #8** 2017-04-25 16:57**MOT test number** 918172005854**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-10-18 15:42**MOT test number** 436776477164**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #6** 2016-04-20 13:55**MOT test number** 194148861101**Result** ✓ Passed**MOT #5** 2015-10-22 16:32**MOT test number** 766291083080**Result** ✓ Passed**MOT #4** 2015-01-26 16:46**MOT test number** 405436625083**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-07-23 16:00**MOT test number** 607824204281**Result** ✓ Passed**MOT #2** 2013-10-15 13:58**MOT test number** 659958483256**Result** ✓ Passed



MOT #1	2013-10-14 15:16
MOT test number	996147583266
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

X

Untaxed

Tax expired:  
1 November 2023

✓

MOT

Expires:  
12 July 2024

Tax status	Expired at 1 November 2023
Days left	179 days too late
MOT expiry date	12 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-13
Last registration	2023-07-13
Complete history	<a href="#">See info</a>



Registration #1	2010-11-13	20 mi
Registration #2	2013-10-14	28.221 mi
Registration #3	2013-10-15	28.221 mi
Registration #4	2014-07-23	34.354 mi
Registration #5	2015-01-26	57.114 mi
Registration #6	2015-10-22	74.233 mi
Registration #7	2016-04-20	80.058 mi
Registration #8	2016-10-18	91.866 mi
Registration #9	2017-04-25	101.486 mi
Registration #10	2018-05-20	111.217 mi
Registration #11	2018-05-20	111.217 mi
Registration #12	2018-05-20	111.217 mi
Registration #13	2018-05-20	111.217 mi
Registration #14	2018-05-20	111.217 mi
Registration #15	2018-05-20	111.217 mi
Registration #16	2018-05-20	111.217 mi
Registration #17	2018-05-20	111.217 mi
Registration #18	2018-05-20	111.217 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	2ZFU254814
---------------	------------