



report date: 2024-03-29

General information

Make	FIAT
Model	500 LOUNGE
Colour	White
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	116 g/km
CO2 label	C






Internet history

Entry 3

Date	2023-02-11
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2

Date	2021-10-03
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](#)

Entry 1

Date	2021-09-29
Pictures	4
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #5	2024-02-07 14:28
MOT test number	417715750207
Result	✓ Passed
Next expiry date	2025-02-09
Advice	SUMP CORRODED
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #4	2023-02-10 14:38
MOT test number	471929521538
Result	✓ Passed

**MOT #3**

2023-02-09 10:23

**MOT test number**

545439773720

**Result****✗ Failed**

**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #2**

2022-06-04 09:39

**MOT test number**

467168891350

**Result****✓ Passed**

**Advice** Rear Tyre slightly damaged/cracking or perishing both tyres cracking through tread (5.2.3 (d) (ii))

**Advice** Front Tyre slightly damaged/cracking or perishing both tyres cracking through tread & on edges (5.2.3 (d) (ii))

**MOT #1**

2021-06-11 13:52

**MOT test number**

274990323650

**Result****✓ Passed**



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
9 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	9 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-13
Last registration	2024-02-07
Complete history	<a href="#">See info</a>



Registration #1	2018-06-13	20 mi
Registration #2	2021-06-11	7.827 mi
Registration #3	2019-06-00	20.000 mi
Registration #4	2019-06-00	20.000 mi
Registration #5	2022-06-04	12.663 mi
Registration #6	2019-06-00	20.000 mi
Registration #7	2019-06-00	20.000 mi
Registration #8	2019-06-00	20.000 mi
Registration #9	2019-06-00	20.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1360 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	2515690