





General information

Make	KIA
Model	SORENTO CRDI KX-3 SAT NAV
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.800 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I







Internet history

Entry 1

Date Pictures 2021-07-28

50

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-11-28
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	4

MOT #11	2022-11-29 14:41
MOT test number	639207778317
Result	Passed
Next expiry date	2023-11-28
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10	2021-08-17 13:27
MOT test number	151358953976
Result	✓ Passed

МОТ #9	2020-12-07 16:05
MOT test number	356319363551
Result	✓ Passed

МОТ #8	2020-12-07 11:26
MOT test number	724759463636
Result	🗙 Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))





MOT #7		2019-12-10 14:45
MOT test r	number	742753147275
Result		✓ Passed
MOT #6		2018-12-17 13:35
MOT test r	number	240181495471
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (2	1.1.14 (a) (ii))

MOT #5	2017-12-15 13:21
MOT test number	623689989077
Result	Passed
Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	

MOT #4	2017-12-14 11:43
MOT test number	278521220601
Result	🗙 Failed
Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure tread on the inside edge and numerous small tears established. (4.1.D.1b)	ure tyre is devoid of
Advice Nearside Rear tyre rubber perished and has cracks formed within the tyre gr	ooves!





MOT #3		2016-12-19 12:32
MOT test i	number	830716951514
Result		✓ Passed
Advice	Offside Rear tyre, devoid of tread on inside edge.	
Advice	Offside Rear tyre, has cracks forming within the tyre grooves.	
Advice	Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Advice Nearside Front Upper Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)		venting the ingress of
Advice	Nearside Rear tyre, has cracks forming within the tyre grooves.	

МОТ #2	2016-12-19 12:32
MOT test number	591098270421
Result	× Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Nearside Rear ty	yre, has cracks forming within the tyre grooves.
Advice Offside Front An	ti-roll bar has slight play in a ball joint (2.4.G.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively
(8.2.2)	
Advice Offside Rear tyre	e, devoid of tread on inside edge.
Advice Nearside Front U	Jpper Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of
dirt (2.4.G.2)	
Advice Offside Rear tyre	e, has cracks forming within the tyre grooves.

MOT #1	2016-01-08 11:29
MOT test number	924893721740
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	X MOT Expired: 28 November 2023
Tax status	Valid until 1 August
Days left	94
MOT expiry date	28 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	 Lashe
Туре	
Damage 2	AMPLE
Damage 2	e e et al
Date	 1.
Category	 AMP
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Number of plates Carrent registration	
Number of plates Carrent registration	
Romber of plates Correct registration Fals since Correct registration	
Rumber of plates Current registration Fals since Fals since Fals since	8000-20-20





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-27
Last registration	2022-11-29
Complete history	See info



Registration #1	2013-01-27	16 mi
Registration #2	2016-01-08	24.936 mi
Registration #3	2016-12-19	32.954 mi
Registration #4	2016-12-19	32.954 mi
Registration #5	2017-12-14	36.545 mi
Registration #6	2017-12-15	36.600 mi
Registration #7	2018-12-17	45.964 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		10.200 mi





Car features

S0225	Air conditionin
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight	
Width	1885 mm
Height	1745 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1919 kg
Max. allowed weight	2510 kg
Additional information	
Fuel tank capacity	64
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Engine number

2

D4HBDH084424