



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Red
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-13
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-09-14
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	33
Total items failed	9

MOT #18	2022-09-10 14:31
---------	------------------

MOT test number	551245757104
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-09-14
------------------	------------

- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Front suspension components corroded but not seriously weakened
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Handbrake needs adjustment
- Advice** Offside Front side mirror secured with tape
- Advice** Front Lower Suspension arm ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Rear suspension components corroded but not seriously weakened
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

**MOT #17**

2022-09-08 14:36

MOT test number

915285235967

Result**✗ Failed**

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Handbrake needs adjustment
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front side mirror secured with tape
- Advice** Front Items removed from driver's view prior to test
- Advice** Front Lower Suspension arm ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Rear suspension components corroded but not seriously weakened
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front suspension components corroded but not seriously weakened

MOT #16

2021-09-14 16:30

MOT test number

645096576901

Result**✓ Passed**

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15** 2020-09-15 16:48**MOT test number** 120551642185**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

MOT #14 2020-09-15 16:48**MOT test number** 426378977681**Result** ✗ Failed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

MOT #13 2019-09-06 10:08**MOT test number** 273938556341**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2018-09-05 15:41**MOT test number** 541285300462**Result** ✓ Passed

**MOT #11** 2017-09-07 08:56**MOT test number** 723298704567**Result** ✓ Passed**Advice** Nearside Front brake disc modified but not seriously weakened (3.5.1n)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2016-09-09 13:25**MOT test number** 201628569188**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit @ 3mm and worn on the inner edge (4.1.E.1)**MOT #9** 2016-09-09 13:25**MOT test number** 319029739672**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit @ 3mm and worn on the inner edge (4.1.E.1)**MOT #8** 2015-09-07 11:23**MOT test number** 106018311294**Result** ✓ Passed**MOT #7** 2014-09-05 13:39**MOT test number** 947138444204**Result** ✓ Passed

**MOT #6** 2014-09-04 12:39**MOT test number** 599297744208**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #5** 2013-09-10 15:44**MOT test number** 725453453222**Result** ✓ Passed**MOT #4** 2013-09-10 11:43**MOT test number** 569683953222**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2012-09-11 12:21**MOT test number** 676795052227**Result** ✓ Passed**MOT #2** 2011-09-07 16:24**MOT test number** 467190151262**Result** ✓ Passed**MOT #1** 2009-03-12 10:33**MOT test number** 474901679012**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 December 2022

✕
MOT

Expired:
14 September 2023

Tax status	Expired at 30 December 2022
Days left	487 days too late
MOT expiry date	14 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	PK06WRR
Plate since	2024-03-29
Current registration	PK06WRR
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-28
Last registration	2022-09-10
Complete history	See info



Registration #1	2006-03-28	21 mi
Registration #2	2009-03-12	27.121 mi
Registration #3	2011-09-07	36.258 mi
Registration #4	2012-09-11	43.516 mi
Registration #5	2013-09-10	51.615 mi
Registration #6	2013-09-10	51.622 mi
Registration #7	2014-09-04	58.505 mi
Registration #8	2014-09-05	58.512 mi
Registration #9	2015-09-07	64.578 mi
Registration #10	2016-09-09	70.142 mi
Registration #11	2016-09-09	70.142 mi
Registration #12	2016-09-09	70.142 mi
Registration #13	2016-09-09	70.142 mi
Registration #14	2016-09-09	70.142 mi
Registration #15	2016-09-09	70.142 mi
Registration #16	2016-09-09	70.142 mi
Registration #17	2016-09-09	70.142 mi
Registration #18	2016-09-09	70.142 mi
Registration #19	2016-09-09	70.142 mi
Registration #20	2016-09-09	70.142 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1025 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4EE6509629