



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D2 BUSINESS EDITION
Colour	Red
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-02
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	0

MOT #12	2023-10-03 14:40
MOT test number	229173657765
Result	✓ Passed
Next expiry date	2024-10-02

MOT #11	2023-09-05 14:11
MOT test number	686752991333
Result	✗ Failed
⚠ DANGEROUS Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))	

MOT #10	2022-12-12 16:15
MOT test number	671535102909
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened ns and os (1.1.14 (a) (ii))
Advice	Offside Front Play in steering rack inner joint(s)
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2022-12-12 09:59**MOT test number** 718747783273**Result** ✗ Failed**Advice** Offside Front Play in steering rack inner joint(s)**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened ns and os (1.1.14 (a) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2021-12-03 08:58**MOT test number** 561967048213**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin ns and os (1.1.13 (a) (ii))**Advice** Nearside Front Nail in tyre**MOT #7** 2020-12-24 11:33**MOT test number** 986724960078**Result** ✓ Passed

**MOT #6** 2020-12-24 09:18**MOT test number** 350343475026**Result** ✗ Failed**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Headlamp aim not tested (4.1.2 (b))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2020-01-28 11:55**MOT test number** 273186299177**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge x2 inner edges (5.2.3 (e))**MOT #4** 2019-03-04 15:44**MOT test number** 197138687222**Result** ✓ Passed**MOT #3** 2018-03-19 13:23**MOT test number** 215680011239**Result** ✓ Passed**MOT #2** 2017-03-14 11:20**MOT test number** 618827448761**Result** ✓ Passed



MOT #1	2016-08-01 10:54
MOT test number	120742896711
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
2 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 DY63KKU
Plate since	2024-03-29
Current registration	 DY63KKU
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-10-11
Last registration	2023-10-03
Complete history	See info



Registration #1	2013-10-11	22 mi
Registration #2	2016-08-01	38.594 mi
Registration #3	2017-03-14	42.243 mi
Registration #4	2018-03-19	53.658 mi
Registration #5	2019-03-04	61.280 mi
Registration #6	2020-01-28	68.761 mi
Registration #7	2020-12-24	72.228 mi
Registration #8	2021-01-29	75.277 mi
Registration #9	2021-02-26	78.277 mi
Registration #10	2021-03-23	81.277 mi
Registration #11	2021-04-20	84.277 mi
Registration #12	2021-05-17	87.277 mi
Registration #13	2021-06-14	90.277 mi
Registration #14	2021-07-11	93.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1570 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4155832