





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	Blue
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-23
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	16
Total items failed	4

MOT #11		2024-02-12 17:38
MOT test	number	344440686867
Result		✓ Passed
Next exp	ry date	2025-02-23
Advice	Hydraulic leak, but not excessive Gearbox. (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Inner Tyre slightly damaged/cracking or perishing And outer edges. (5.2.3 (d) (ii))		
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing Wall and between the treads.		
(5.2.3 (d)	(II))	
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing And or	uter edges. (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number
795797922407

Result

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing Cracking between the treads. (5.2.3 (d) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2023-02-16 14:45 **MOT** test number 376943768076 Result × Failed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing Cracking between the treads. (5.2.3 (d) (ii)) Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a)) **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2022-02-24 13:29
MOT test number	449131904010
Result	✓ Passed
MOT #7	2020-12-10 14:30
MOT test number	856705390184
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6 2020-12-09 12:54

MOT test number 195393391032

Result × Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #5 2019-06-27 12:29

MOT test number 643144529279

Result ✓ Passed

MOT #4 2018-06-20 13:30

MOT test number 635389987011

Result ✓ Passed

MOT #3 2017-06-19 07:59

MOT test number 316083336926

Result \(\sqrt{Passed} \)

MOT #2 2016-06-21 07:54

MOT test number 790685501968

Result

Passed

MOT #1 2015-06-30 11:01

MOT test number 858541785173

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 23 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

^ -		histor	-
- () ()	vnor	nictor	٦.
\smile	VIICI	пизсоп	·v

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
manage of the same	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK 212
Plate since	
	More info >

CarCheck.co.uk page 9/12



KW12AOE report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-30
Last registration	2024-02-12
Complete history	See info



Registration #1	2012-06-30	14 mi
Registration #2	2015-06-30	11.561 mi
Registration #3	2016-06-21	12.510 mi
Registration #4	2017-06-19	12.863 mi
Registration #5	2018-06-20	13.839 mi
Registration #6	2019-06-27	18.905 mi
Registration #7	2020-12-09	32.788 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number G4LACM870481