



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D3 ES
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history


Entry 2

Date	2021-07-21
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-07-20
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-04
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	3

MOT #15	2024-02-05 09:49
MOT test number	570727656720
Result	✓ Passed
Next expiry date	2025-02-04
Advice	Central Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2024-02-05 09:49
MOT test number	804626342362
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #13** 2023-01-25 08:59**MOT test number** 309701526166**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-08-10 10:27**MOT test number** 546262528547**Result** ✓ Passed**MOT #11** 2021-08-05 10:18**MOT test number** 807866493924**Result** ✗ Failed**Fail** Front Steering rack gaiter missing or no longer prevents the ingress of dirt Both sides insecure (2.1.3 (g) (ii))**MOT #10** 2020-09-25 09:35**MOT test number** 849444205266**Result** ✓ Passed**MOT #9** 2019-10-03 09:06**MOT test number** 189515467754**Result** ✓ Passed

**MOT #8** 2019-04-15 09:58**MOT test number** 726075165399**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))**MOT #7** 2019-01-15 16:55**MOT test number** 721873815729**Result** ✓ Passed**MOT #6** 2019-01-15 11:18**MOT test number** 453605519172**Result** ✗ Failed**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2018-01-25 11:04**MOT test number** 737489580782**Result** ✓ Passed**MOT #4** 2017-01-21 10:17**MOT test number** 216960054557**Result** ✓ Passed**MOT #3** 2016-01-19 13:05**MOT test number** 895532710372**Result** ✓ Passed



MOT #2	2015-01-27 13:55
MOT test number	196387425030
Result	✓ Passed

MOT #1	2014-03-12 16:50
MOT test number	569341374060
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
4 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	4 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-31
Last registration	2024-02-05
Complete history	<a href="#">See info</a>



Registration #1	2011-03-31	10 mi
Registration #2	2014-03-12	22.511 mi
Registration #3	2015-01-27	25.081 mi
Registration #4	2016-01-19	30.578 mi
Registration #5	2017-01-21	39.067 mi
Registration #6	2018-01-25	49.188 mi
Registration #7	2019-01-15	59.465 mi
Registration #8	2019-01-15	59.465 mi
Registration #9	2019-04-15	61.723 mi
Registration #10	2019-05-20	61.723 mi
Registration #11	2019-05-20	61.723 mi
Registration #12	2019-05-20	61.723 mi
Registration #13	2019-05-20	61.723 mi
Registration #14	2019-05-20	61.723 mi
Registration #15	2019-05-20	61.723 mi
Registration #16	2019-05-20	61.723 mi
Registration #17	2019-05-20	61.723 mi
Registration #18	2019-05-20	61.723 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1504 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1012435