



**LG64VVT**


report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2014
Top speed	90 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-01
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	25
Total items failed	21

MOT #11	2023-09-20 09:53
MOT test number	744388615785
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Horn weak
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2023-09-15 09:09

**MOT test number**

852089667256

**Result****✗ Failed**

- Fail** Brake cable guide defective and affecting operation (1.1.15 (d))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Exhaust system insecure Resting on rear sub frame (6.1.2 (a))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Headlamp aim unable to be tested (4.1.2 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Horn weak
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #9** 2022-08-26 13:27**MOT test number** 248610315057**Result** ✓ Passed**Advice** Offside Front Outer drive shaft boot leaking**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #8** 2022-08-26 13:27**MOT test number** 898757328027**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Outer drive shaft boot leaking**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #7** 2021-06-25 10:54**MOT test number** 980760563907**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2021-06-24 10:09**MOT test number** 158358050317**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2020-07-15 10:33**MOT test number** 520255297308**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #4** 2019-06-18 13:25**MOT test number** 712999028632**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2018-06-05 09:11**MOT test number** 545473093752**Result** ✓ Passed**MOT #2** 2017-08-29 12:36**MOT test number** 977952668838**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1

2017-08-29 12:36

MOT test number

617868776091

Result		✗ Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	
Pass with rectification	Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Pass with rectification	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
19 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	19 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-10-21
Last registration	2023-09-20
Complete history	<a href="#">See info</a>



Registration #1	2014-10-21	10 mi
Registration #2	2017-08-29	27.326 mi
Registration #3	2017-08-29	27.326 mi
Registration #4	2018-06-05	37.049 mi
Registration #5	2019-06-18	49.994 mi
Registration #6	2020-07-15	60.254 mi
Registration #7	2021-06-24	61.240 mi
Registration #8	2022-05-20	61.240 mi
Registration #9	2022-05-20	61.240 mi
Registration #10	2022-05-20	61.240 mi
Registration #11	2022-05-20	61.240 mi
Registration #12	2022-05-20	61.240 mi
Registration #13	2023-09-20	61.240 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1673 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	JBDF0042531