



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D R-DESIGN
Colour	Red
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-07-07
Pictures	46
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-03
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	27
Total items failed	16

MOT #19	2023-06-30 14:05
MOT test number	112212270945
Result	✓ Passed
Next expiry date	2024-07-03

MOT #18	2023-06-19 08:17
MOT test number	276751484213
Result	✗ Failed
Fail	Nearside Rear Exhaust has a major leak of exhaust gases BACK BOX GOT HOLE (6.1.2 (a))
Fail	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm ALSO THREAD EXPOSED (5.2.3 (e))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Central Brake lever has insufficient reserve travel (1.1.2 (a))

MOT #17	2022-07-04 15:19
MOT test number	380439533675
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2022-07-04 12:09

MOT test number

804169511463

Result**✗ Failed****Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #15**

2021-09-24 11:23

MOT test number

170515036042

Result**✓ Passed****Advice** Offside Rear Brake pipe corroded, covered in grease or other material Connector/ attachment point (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edges/ shoulders (5.2.3 (e))**MOT #14**

2021-09-24 11:23

MOT test number

823424667512

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edges/ shoulders (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Connector/ attachment point (1.1.11 (c))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #13**

2020-09-19 15:21

MOT test number

126683551896

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (No bulb inside holder and contacts broken away - Requires new bulb holder - Advise to replace at earliest convenience) (4.7.1 (b) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge Badly worn on inner edge - Advise to replace as soon as possible (5.2.3 (e))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated Advise to replace at earliest convenience (6.1.7 (g) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Exhaust system starting to corrode**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Badly worn on inner edge - Advise to replace as soon as possible (5.2.3 (e))**MOT #12**

2019-09-26 15:58

MOT test number

534440755289

Result

✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2019-09-26 10:37

MOT test number

299055512266

Result

✗ Failed

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #10** 2018-11-30 17:10**MOT test number** 846943099251**Result** ✓ Passed**MOT #9** 2018-11-30 09:49**MOT test number** 632095600548**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2017-11-30 10:49**MOT test number** 571758790685**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 2.5mm left (4.1.E.1)**MOT #7** 2017-11-30 10:49**MOT test number** 103199897175**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit 2.5mm left (4.1.E.1)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2016-11-30 15:09**MOT test number** 816581958607**Result** ✓ Passed**MOT #5** 2016-03-09 09:44**MOT test number** 683246096095**Result** ✓ Passed

**MOT #4** 2016-03-09 09:44**MOT test number** 243512148424**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2015-03-18 10:34**MOT test number** 959887875019**Result** ✓ Passed**MOT #2** 2014-03-25 11:13**MOT test number** 285294884057**Result** ✓ Passed**MOT #1** 2013-03-19 11:59**MOT test number** 646478273089**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Rear tyres out of shape**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
3 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX10XWE
Plate since	2019-09-29
Current registration	YX10XWE
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-03-24
Last registration	2023-06-30
Complete history	See info



Registration #1	2010-03-24	17 mi
Registration #2	2013-03-19	29.801 mi
Registration #3	2014-03-25	37.827 mi
Registration #4	2015-03-18	44.346 mi
Registration #5	2016-03-09	50.311 mi
Registration #6	2016-03-09	50.311 mi
Registration #7	2016-11-30	54.489 mi
Registration #8	2017-11-30	63.577 mi
Registration #9	2017-11-30	63.577 mi
Registration #10	2018-11-30	74.264 mi
Registration #11	2018-11-30	74.264 mi
Registration #12	2019-06-30	75.277 mi
Registration #13	2019-06-30	75.277 mi
Registration #14	2019-06-30	75.277 mi
Registration #15	2019-06-30	75.277 mi
Registration #16	2019-06-30	75.277 mi
Registration #17	2019-06-30	75.277 mi
Registration #18	2019-06-30	75.277 mi
Registration #19	2019-06-30	75.277 mi
Registration #20	2019-06-30	75.277 mi
Registration #21	2019-06-30	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1430 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	746796