



PEUGEOT



KP06FYD


report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 FELINE (180BHP)
Colour	Grey
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	202 Nm at 4.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	43.5 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-07-23
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2021-11-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	34
Total items failed	4

MOT #13 2020-11-23 09:24

MOT test number 200359093155

Result ✓ Passed

Next expiry date 2021-11-24

**Advice** Engine cooling fan does not work!

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded on inner and outer face! (1.1.14 (a) (ii))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded on inner and outer face! (1.1.14 (a) (ii))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded on inner and outer face! (1.1.14 (a) (ii))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded on inner and outer face! (1.1.14 (a) (ii))

MOT #12 2019-11-25 14:17

MOT test number 573390755437

Result ✓ Passed

**MOT #11**

2018-02-06 09:03

**MOT test number**

229354889688

**Result**

✓ Passed

**Advice**

Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Both front tyres cracked between treads and on walls

**Advice**

Both rear discs corroded slightly

**Advice**

Central Exhaust has a minor leak of exhaust gases to rear joint (7.1.2)

**Advice**

Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Both front discs corroded slightly

**Advice**

Rear exhaust deteriorated slightly

**MOT #10**

2018-02-06 09:03

**MOT test number**

354806724584

**Result**

✗ Failed

**Advice**

Both front tyres cracked between treads and on walls

**Advice**

Both rear discs corroded slightly

**Advice**

Central Exhaust has a minor leak of exhaust gases to rear joint (7.1.2)

**Advice**

Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Both front discs corroded slightly

**Advice**

Rear exhaust deteriorated slightly

**Pass with rectification**

Battery insecure (1.9.1)

**Advice**

Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2015-11-07 09:59**MOT test number** 605959097154**Result** ✓ Passed**Advice** Both rear discs corroded slightly**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Both front discs corroded slightly**MOT #8** 2014-09-06 10:47**MOT test number** 589889644212**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** All four discs corroded slightly**MOT #7** 2013-08-01 15:06**MOT test number** 975913813262**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2013-08-01 11:56**MOT test number** 297303613217**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Battery insecure (1.9.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)

**MOT #5** 2012-08-02 16:28**MOT test number** 929325912257**Result** ✓ Passed**Notice** Front disks slightly corroded**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear rear brake grabbing slightly (3.7.A.5b)**MOT #4** 2012-08-02 16:28**MOT test number** 837445212239**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front disks slightly corroded**Pass with rectification** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)**Advice** Offside Rear rear brake grabbing slightly (3.7.A.5b)**MOT #3** 2011-07-30 11:52**MOT test number** 846931711291**Result** ✓ Passed**MOT #2** 2010-07-24 10:50**MOT test number** 321755800207**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-07-25 10:45**MOT test number** 363736809247**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2006-04-04
Last registration	2020-11-23
Complete history	<a href="#">See info</a>



Registration #1	2006-04-04	27 mi
Registration #2	2009-07-25	18.585 mi
Registration #3	2010-07-24	21.720 mi
Registration #4	2011-07-30	24.003 mi
Registration #5	2012-08-02	25.689 mi
Registration #6	2013-08-01	26.423 mi
Registration #7	2013-08-01	26.423 mi
Registration #8	2015-05-20	26.277 mi
Registration #9	2015-05-20	26.277 mi
Registration #10	2015-05-20	26.277 mi
Registration #11	2015-05-20	26.277 mi
Registration #12	2015-05-20	26.277 mi
Registration #13	2015-05-20	26.277 mi
Registration #14	2015-05-20	26.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1361 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	LH3L1314847