



report date: 2024-03-28

General information

Make	MINI
Model	COOPER D
Colour	Blue
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-08-08
Pictures	18
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-14
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	8
Total items failed	7

MOT #12	2023-08-04 08:13
MOT test number	998364750876
Result	✓ Passed
Next expiry date	2024-08-14

MOT #11	2022-08-15 08:48
MOT test number	869405666983
Result	✓ Passed

MOT #10	2022-08-03 14:09
MOT test number	299190099651
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Obligatory mirror insecure (3.3 (b) (ii))

MOT #9	2022-01-25 16:35
MOT test number	702075715150
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Slightly out of shape (5.2.3 (d) (ii))

**MOT #8** 2022-01-25 16:35**MOT test number** 503716661700**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slightly out of shape (5.2.3 (d) (ii))**MOT #7** 2021-01-28 16:46**MOT test number** 435977904800**Result** ✓ Passed**MOT #6** 2021-01-28 11:28**MOT test number** 621551158677**Result** ✗ Failed**Minor** Windscreen seriously discoloured but not adversely affecting driver's view (3.2 (a) (i))**Fail** Headlamp aim too low (4.1.2 (a))**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #5** 2020-01-15 10:04**MOT test number** 930916426448**Result** ✓ Passed



MOT #4 2019-01-09 10:10

MOT test number 427149604685

Result ✓ Passed

MOT #3 2017-10-12 12:33

MOT test number 670765515714

Result ✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2 2017-01-12 17:20

MOT test number 113461742803

Result ✓ Passed

MOT #1 2016-01-26 17:03

MOT test number 135053549656

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
14 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	14 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-01-24
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2014-01-24	22 mi
Registration #2	2016-01-26	25.185 mi
Registration #3	2017-01-12	35.726 mi
Registration #4	2017-10-12	44.085 mi
Registration #5	2019-01-09	51.752 mi
Registration #6	2020-01-15	57.618 mi
Registration #7	2021-01-28	61.141 mi
Registration #8	2022-01-28	65.277 mi
Registration #9	2022-01-28	65.277 mi
Registration #10	2022-01-28	65.277 mi
Registration #11	2022-01-28	65.277 mi
Registration #12	2022-01-28	65.277 mi
Registration #13	2022-01-28	65.277 mi
Registration #14	2023-08-04	65.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70898648