



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 SPORT DCI S/R P/V
Colour	Silver
Year of manufacture	2010
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-22
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-09
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	22
Total items failed	13

MOT #15	2023-12-16 13:20
MOT test number	920616764827
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view Stone chipped (3.2 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #14	2023-01-07 14:40
MOT test number	507712119009
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2022-01-10 14:17
MOT test number	412469691701
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12**

2022-01-06 13:00

MOT test number

998585188513

Result**✗ Failed**

- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Central Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Rear Brake pipe excessively corroded all rear steel pipes (1.1.11 (c))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11

2021-01-06 14:45

MOT test number

671572165080

Result**✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2021-01-05 12:00

MOT test number

548654078368

Result**✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2019-07-02 11:53

MOT test number

227348401373

Result**✓ Passed****MOT #8**

2019-07-02 11:53

MOT test number

151402171679

Result**✗ Failed**

- Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))
- Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Pass with rectification** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))

**MOT #7** 2018-05-23 14:40**MOT test number** 965841659157**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #6** 2017-05-31 08:45**MOT test number** 118104977237**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2016-05-27 08:44**MOT test number** 421789909508**Result** ✓ Passed**MOT #4** 2015-05-26 12:02**MOT test number** 208376645410**Result** ✓ Passed**MOT #3** 2014-05-30 13:38**MOT test number** 796270754115**Result** ✓ Passed**MOT #2** 2014-05-29 15:50**MOT test number** 965859844121**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



MOT #1	2013-07-25 11:21
MOT test number	468406403258
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 February
-------------------	------------------------

Days left	277
------------------	-----

MOT expiry date	9 January 2025
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-08-10
Last registration	2023-12-16
Complete history	See info



Registration #1	2010-08-10	10 mi
Registration #2	2013-07-25	76.371 mi
Registration #3	2014-05-29	93.099 mi
Registration #4	2014-05-30	93.099 mi
Registration #5	2015-05-26	111.107 mi
Registration #6	2016-05-27	128.454 mi
Registration #7	2017-05-31	145.449 mi
Registration #8	2018-05-23	155.070 mi
Registration #9	2019-07-02	175.906 mi
Registration #10	2020-05-20	191.377 mi
Registration #11	2021-05-20	207.377 mi
Registration #12	2022-05-20	223.377 mi
Registration #13	2023-05-20	239.377 mi
Registration #14	2024-05-20	255.377 mi
Registration #15	2025-05-20	271.377 mi
Registration #16	2026-05-20	287.377 mi
Registration #17	2027-05-20	303.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1955 mm
Length	5182 mm
Kerb weight	1660 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C074090