



report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI S LINE
Colour	Black
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	320 Nm at 2.100 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	51.4 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2024-06-03
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	37
Total items failed	3

MOT #16	2023-05-27 13:27
MOT test number	580866879753
Result	✓ Passed
Next expiry date	2024-06-03
Advice	Rear Tyre worn close to legal limit/worn on edge Both rear (5.2.3 (e))

MOT #15	2022-05-14 11:41
MOT test number	364443050296
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))

**MOT #14**

2021-06-02 14:57

**MOT test number**

805074462927

**Result**

✓ Passed

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement BOTH sides (5.3.4 (a) (i))

**Advice** Front Lower Suspension arm damaged but not seriously weakened BOTH sides (5.3.3 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-06-02 09:57

**MOT test number**

612717230184

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Front Lower Suspension arm damaged but not seriously weakened BOTH sides (5.3.3 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Upper Suspension arm pin or bush worn but not resulting in excessive movement BOTH sides (5.3.4 (a) (i))

**MOT #12**

2020-06-04 08:12

**MOT test number**

685425741271

**Result**

✓ Passed

**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**Advice** Under trays fitted

**Advice** Offside Rear Nail in tyre

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11** 2019-07-05 14:14**MOT test number** 915445177306**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2018-07-24 11:31**MOT test number** 153794904242**Result** ✓ Passed**Advice** Undertray and engine cover fitted**Advice** Front numberplate deteriorating**MOT #9** 2017-09-06 14:17**MOT test number** 286828589019**Result** ✓ Passed**Advice** Emissions to clean to test**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Under tray fitted**Advice** Offside Front Upper Suspension arm has slight play in a ball joint rear arm (2.4.G.2)**MOT #8** 2017-09-06 13:02**MOT test number** 220614643181**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint front (2.4.G.2)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Under tray fitted**Advice** Offside Front Upper Suspension arm has slight play in a ball joint rear arm (2.4.G.2)**Advice** Emissions to clean to test

**MOT #7** 2016-09-12 10:51**MOT test number** 618850335537**Result** ✓ Passed**Advice** Vehicle has engine cover fitted unable to carry out full inspection of engine bay**Advice** Emissions to clean to test**Advice** Vehicle has under trays fitted unable to carry out full inspection**MOT #6** 2016-09-12 10:00**MOT test number** 211595842261**Result** ✗ Failed**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Vehicle has under trays fitted unable to carry out full inspection**Advice** Vehicle has engine cover fitted unable to carry out full inspection of engine bay**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Emissions to clean to test**MOT #5** 2015-08-24 14:05**MOT test number** 596789892177**Result** ✓ Passed**MOT #4** 2014-08-28 13:59**MOT test number** 918280044231**Result** ✓ Passed**MOT #3** 2013-09-07 10:41**MOT test number** 179270053275**Result** ✓ Passed



MOT #2	2012-09-08 15:21
MOT test number	499482952228
Result	✓ Passed

MOT #1	2011-09-08 09:37
MOT test number	786561751273
Result	✓ Passed

**Notice** Both rear tyres getting low on outside edges



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
3 June 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	3 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-12
Last registration	2023-05-27
Complete history	<a href="#">See info</a>



Registration #1	2008-09-12	10 mi
Registration #2	2011-09-08	22.006 mi
Registration #3	2012-09-08	36.538 mi
Registration #4	2013-09-07	65.959 mi
Registration #5	2014-08-28	83.565 mi
Registration #6	2015-08-24	92.420 mi
Registration #7	2016-09-12	100.148 mi
Registration #8	2016-09-12	100.148 mi
Registration #9	2017-09-06	104.503 mi
Registration #10	2018-05-22	111.277 mi
Registration #11	2019-05-22	111.277 mi
Registration #12	2020-05-22	111.277 mi
Registration #13	2021-05-22	111.277 mi
Registration #14	2022-05-22	111.277 mi
Registration #15	2023-05-27	111.277 mi
Registration #16	2023-05-27	111.277 mi
Registration #17	2023-05-27	111.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1460 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	CAG 131084