





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI HIGHLINE BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2016
Top speed	106 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



FE66VLS

report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-09-02

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2024-11-28
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	4
Total items failed	4
MOT #7	2023-11-16 10:12
MOT test number	115018405074
Result	<b>✓</b> Passed
Next expiry date	2024-11-28
MOT #6	2022-11-29 17:07
MOT test number	613530899516
Result	<b>✓</b> Passed

MOT #5	2021-10-21 08:54
MOT test number	969428923626
Result	<b>√</b> Passed

MOT #4	2021-06-22 12:07
MOT test number	455127567060
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2021-06-22 08:35

**MOT test number** 842472561083

Result X Failed

Advice Rear Undertray not fully secure (8.1.1 (b) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2020-06-29 13:43

**MOT test number** 617177872026

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #1** 2019-09-06 08:22

**MOT test number** 272001605892

**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect shock ,leaking

(5.3.2 (b))

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	28 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



FE66VLS

report date: 2024-03-28

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

Damage 2

Category

**Type** 

Date

Туре



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



FE66VLS

report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
********	
***************************************	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

**Finance company Date of agreement Agreement type** Agreement term **Agreement number** 

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-08
Last registration	2023-11-16
Complete history	See info



Registration #1	2016-09-08	27 mi
Registration #2	2019-09-06	39.505 mi
Registration #3	2020-06-29	46.202 mi
Registration #4	2021-06-22	63.878 mi
Registration #5	2021-06-22	63.878 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



# Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3 mm
Kerb weight	1594 kg
Max. allowed weight	2299 kg

### Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	2
Number of axles	2
Engine number	DFSD084278