





report date: 2024-03-28

General information

Make	VAUXHALL
Model	ZAFIRA SRI NAV
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-24
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	21
Total items failed	1

MOT #6		2024-03-25 16:17
MOT test	number	644890544145
Result		✓ Passed
Next expi	ry date	2025-03-24
Advice	Front Brake disc worn, but not excessively lipped (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside outer sill damaged	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Tyre slightly damaged/cracking or perishing both n/s and o/s tyres (5.2.3	(d) (ii))
Advice	Nearside Front Upper strut mount bush/bearing worn	
Advice	Rear Brake disc worn, but not excessively lipped (1.1.14 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



Result

NI67HIU report date: 2024-03-28

MOT #5 2024-03-22 16:52

MOT test number 165998523925

× Failed **Advice** Rear Tyre slightly damaged/cracking or perishing both n/s and o/s tyres (5.2.3 (d) (ii)) **Advice** Front Brake disc worn, but not excessively lipped (1.1.14 (a) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside outer sill damaged Advice Front Tyre slightly damaged/cracking or perishing both n/s and o/s tyres (5.2.3 (d) (ii)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Upper strut mount bush/bearing worn

Advice Rear Brake disc worn, but not excessively lipped (1.1.14 (a) (i))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure on outer wall, also has cords exposed (5.2.3 (d) (ii))

MOT #4 2023-03-08 08:56

740980750446 **MOT** test number

Result Passed

Advice Nearside outer sill damaged

Advice Nearside Rear Nail in tyre

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #3 2022-03-10 16:51

MOT test number 682601567348

Result ✓ Passed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/12



MOT #2	2021-03-16 07:38
MOT test number	190289497641
Result	✓ Passed
MOT #1	2020-06-22 11:22
MOT test number	692961400911
MOT test number	092901400911

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

,00,-
,00,-
00,-
,00,-
,50,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-22
Last registration	2024-03-25
Complete history	See info



Registration #1	2017-09-22	6 mi
Registration #2	2020-06-22	54.499 mi
Registration #3		11.777 es
Registration #4	2021-03-16	60.032 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1685 mm
Length	4666 mm
Wheel base	2760 mm
Kerb weight	1538 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	B14NET -19RE9095LUJ

CarCheck.co.uk page 12/12