





report date: 2024-03-29

General information

Make	NISSAN
Model	370 Z V6 GT EDITION
Colour	White
Year of manufacture	2012
Top speed	155 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	328 BHP
Max. torque	363 Nm at 5.200 rpm
Engine capacity	3.696 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.8 mpg
Consumption combined	26.7 mpg
CO2 emission	248 g/km
CO2 label	L



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date	2022-08-09
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-15
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2025-03-18
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #12	2024-03-19 13:51
MOT test number	785015484242
Result	√ Passed
Next expiry date	2025-03-18

MOT #11	2023-07-10 15:09
MOT test number	618784064365
Result	✓ Passed

MOT #10		2023-07-05 10:56
MOT test	number	139366025063
Result		× Failed
MAJOR	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #9	2022-10-21 14:29
MOT test number	580670888127
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2022-10-06 16:40 967147075761 **MOT** test number Result × Failed **Advice** Bonnet pull handle broken cable ok **MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Rear blade split **DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Front pipe heat shields corroded loose **MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6		2020-10-05 13:18
MOT test	number	586747370232
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice

Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

 MOT #4
 2018-09-24 08:45

 MOT test number
 245494962201

 Result
 ✓ Passed

 MOT #3
 2017-09-09 10:18

 MOT test number
 684514560290

Result \sqrt{Passed}

Advice Offside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

 MOT #2
 2016-10-01 10:45

 MOT test number
 274398379738

 Result
 ✓ Passed

Advice Full inspection of under body and under bonnet components not possible, covers fitted

 MOT #1
 2015-10-05 08:22

 MOT test number
 665178060980

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax expired:
31 December 2022



Tax status	Expired at 31 December 2022
Days left	486 days too late
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra NISSAN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NIP. IUK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-05
Last registration	2024-03-19
Complete history	See info



Registration #1	2012-10-05	6 mi
Registration #2	2015-10-05	18.267 mi
Registration #3	2016-10-01	28.068 mi
Registration #4	2017-09-09	43.440 mi
Registration #5	2018-09-24	53.593 mi
Registration #6	2019-10-01	62.937 mi
Registration #7	2020-10-05	71.691 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1845 mm
Height	1315 mm
Length	4250 mm
Wheel base	2550 mm
Kerb weight	1496 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	72 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	67673A

CarCheck.co.uk page 12/12